

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: DIRTY [x]
<b>Owner :</b>		<b>Mileage :</b>	197608 KM
<b>File nr. :</b>	1446121	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1CVO779 / WDF63960113722812 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	07/03/2012
<b>VFS-nr. :</b>		<b>Color :</b>	RED
<b>Make + Model :</b>	MERCEDES / VITO	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	12314	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	MIELE NV 421000/800	<b>Co2:</b>	206g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	IMITATION LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	VITO 110 B/F SWB 95PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	2143
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	3
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	95	<b>kW:</b>	70
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	[x]
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	16	
Rear tyre	195	65	R	16	

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] FRONT MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR

[x] ROOF/CENTER/RIGHT OTHER DAMAGES HAGEL

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] FRONT THRESHOLD/LEFT/FRONT DENT

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	232.88 EUR		50 %	232.88 EUR

[x] BONNET/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	217.56 EUR		50 %	217.56 EUR

[x] FRONT BUMPER/LEFT/CORNER SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	110.64 EUR

### Interior

[x] SEAT FL HOLE

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-intvnl-01	VINYL REPAIR	82.20 EUR	82.20 EUR
Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-intvnl-01	VINYL REPAIR	82.20 EUR	82.20 EUR

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	45.88 EUR

1	2	3	4	5	6	7	8	9	10
45.88	110.64	217.56	232.88	231.15	164.40	0	0	0	0
45.88	110.64	108.78	116.44	115.58	164.40	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
320.92	681.59	0	<b>1002.51</b>
HOG: 0	BG: 3		NA Deprec. 661.72
			0.00%
			<b>TOTAL 661.72</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 13/10/2017 <b>Hour :</b> 10:18 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	