

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	136153 KM
File nr. :	1447242	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
WD8569 / VF30ERHHAES145252 /		yr of constructionr :	/
E-File nr. :		First registration :	04/08/2014
VFS-nr. :		Color :	BLACK
Make + Model :	PEUGEOT / 5008	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	
Variant car:	MONOVOLUME	Engine size:	1997
Gear box :	Automaat algemeen	Number of places:	7
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	DUNLOP	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	DUNLOP	Tyre :	[x] OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	DUNLOP	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	70	R	17	M+S
Rear tyre	215	70	R	17	M+S

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :			/	Hubcap :
Wheel RL :			Tyre :	OK	/	Rim :			/	Hubcap :
Wheel FR :			Tyre :	OK	/	Rim :			/	Hubcap :
Wheel RR :			Tyre :	OK	/	Rim :			/	Hubcap :
Wheel RES:			Tyre :	OK	/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE		
[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)		
[x]	REAR MUDGUARD/LEFT/CENTER	DENT	X4	
[x]	REAR DOOR/LEFT/FRONT	DENT	X2	
[x]	FRONT MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT THRESHOLD/LEFT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	40 LU =192.00 EUR	0 EUR	414.00 EUR	50 %	606.00 EUR
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

Interior

[x]	BOOT LID IN	CARVED			
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	UPHOLSTERY DOOR	90.00 EUR	50 %	90.00 EUR

Number	Code	Description	Unit price	Depr.	Total
2	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR

Number	Code	Description	Unit price	Depr.	Total
3	1	DOORSTEP	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
114.00	487.20	856.00	380.00	0	0	0	0	0	0
57.00	243.60	428.00	380.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
380.00	1457.20	0	1837.20
HOG: 0	BG: 0		NA Deprec. 1108.60
			0.00%
			TOTAL 1108.60

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : DOC WORDEN NAGESTUURD [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 13:02 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	