

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	78413 KM
File nr. :	1440295	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1AJA108 / VF34C9HR8BS013799 /		yr of constructionr :	/
E-File nr. :		First registration :	20/01/2011
VFS-nr. :		Color :	BLUE
Make + Model :	PEUGEOT / 308	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	GEMEENTE ETTERBEEK	Co2:	119g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	308 BER Premium FAP 112PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	112	kW:	82
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] GOODYEAR Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RL : [x] UNIROYAL Tyre : OK [x] >6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] GOODYEAR Tyre : [x] OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] UNIROYAL Tyre : OK [x] >6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	15	T
Rear tyre	205	55	R	15	T

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	OTHER DAMAGES	AFDEKKING TREKOOG		
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	0 EUR		50 %	
[x]	REAR DOOR/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	+DEUK		
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	REAR DOOR/LEFT/FRONT	DENT	2X		
	Number Code	Description	Unit price	Depr.	Total
6	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	Number Code	Description	Unit price	Depr.	Total
6	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR
[x]	ROOF/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	+DEUKEN + KRASSEN GANS HET DAK		
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR
[x]	REAR DOOR/RIGHT/CENTER	DENT	3X		
	Number Code	Description	Unit price	Depr.	Total
10	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	Number Code	Description	Unit price	Depr.	Total
10	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR
	Number Code	Description	Unit price	Depr.	Total
10	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x]	BONNET/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	FRONT MUDGUARD/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/LEFT		SCRATCH WITH PAINT DAMAGE		
	Number Code	Description	Unit price	Depr.	Total
0	0				
[x]	FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		58.32 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02 REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02 REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02 REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02 REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
8	1	FIXATION COVER	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
58.32	380.00	211.80	290.08	318.35	82.80	481.50	331.68	308.20	322.78
58.32	380.00	105.90	145.04	159.18	82.80	240.75	165.84	154.10	212.69

INNOVATIVE	TRADITIONAL	GENERAL	
623.72	2161.79	0	2785.51
HOG: 0	BG: 0		NA Deprec. 1704.62
			0.00%
			TOTAL 1704.62

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 14:38 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	