

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

|                                     |   |                                 |                               |
|-------------------------------------|---|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING                               | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: CLEAN [x] |
| <b>Owner :</b>                      |   | <b>Mileage :</b>                | 107147 KM                     |
| <b>File nr. :</b>                   | 1447731                                       | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |   | <b>Mileag ref. service :</b>    | 0                             |
| 1EBU817 / W0LPE9EM2D2005824 /       |   | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |   | <b>First registration :</b>     | 15/10/2012                    |
| <b>VFS-nr. :</b>                    |   | <b>Color :</b>                  | BROWN                         |
| <b>Make + Model :</b>               | OPEL / ZAFIRA                                 | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 | 12406   | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             |   | <b>Environment Class:</b>       | EURO 5                        |
| <b>Customer company :</b>           | GEA PROCESS<br>ENGINEERING/COURTOY<br>(HALLE) | <b>Co2:</b>                     | 119g/km                       |
| <b>Driver :</b>                     |   | <b>Remote controls:</b>         | 2                             |
| <b>Covering :</b>                   | TISSUE-LEATHER                                | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle kind :</b>               | VEHICLE                                       | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               | ZAFIRA TOURER ecoFL.Cosmo St/St.130PK         | <b>Country registration :</b>   | BELGIUM                       |

|                                     |         |                            |         |
|-------------------------------------|---------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   | No      | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 |         | <b>Engine size:</b>        | 1956    |
| <b>Gear box :</b>                   | Manueel | <b>Number of places:</b>   | 5       |
| <b>Number of gears:</b>             | 6       | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 131     | <b>kW:</b>                 | 96      |
| <b>Fisc HP</b>                      |         | <b>Imported vehicle:</b>   | No      |
| <b>Animals transported:</b>         | No      | <b>Smoked in vehicle:</b>  | No      |
| <b>Due date vehicle inspection:</b> |         | <b>Extra set of tires:</b> | No      |
|                                     |         | <b>Use:</b>                | Unknown |

**General condition:**

|                              |    |                       |                         |        |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number :   | OK | Service manual :      | OK                      | [x]    |
| Cert. of reg. / Part 1:      |    | Cert. of conformity : | OK                      |        |
| Cert. of reg. copy / Part 2: | OK | [x]                   | Insurance certificate : |        |
| Warning vest :               | OK | [x]                   | Transport licence :     |        |
| Tax certificate :            |    |                       | Navigation CD/SD/DVD    | OK [x] |
| Fuel card :                  |    |                       | Car radio :             | OK [x] |
| Mobile phone kit :           |    |                       | Extinguisher :          | OK [x] |
| First aid kit :              | OK | [x]                   | Warning triangle :      | OK [x] |
| Jack, wheelspanner :         |    |                       | Oil level :             | OK [x] |
|                              |    |                       | Filled up :             | 0      |

## Wheels and tyres: Summer tires

|            |     |        |        |     |     |      |       |       |          |          |
|------------|-----|--------|--------|-----|-----|------|-------|-------|----------|----------|
| Wheel FL:  | [x] | KLÉBER | Tyre : | OK  | [x] | 4-6/ | Rim : | /     | Hubcap : |          |
| Wheel RL : | [x] | KLÉBER | Tyre : | OK  | [x] | 4-6/ | Rim : | /     | Hubcap : |          |
| Wheel FR : | [x] | KLÉBER | Tyre : | [x] | OK  | [x]  | 4-6/  | Rim : | /        | Hubcap : |
| Wheel RR : | [x] | KLÉBER | Tyre : | OK  | [x] | 4-6/ | Rim : | /     | Hubcap : |          |
| Wheel RES: | [x] |        | Tyre : | OK  |     | /    | Rim : | /     | Hubcap : |          |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225   | 50     | R    | 17  | W     |
| Rear tyre  | 225   | 50     | R    | 17  | W     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |   |          |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                          |                           |                      |              |              |
|-----|--------------------------|---------------------------|----------------------|--------------|--------------|
| [x] | REAR BUMPER/CENTER/RIGHT | SCRATCH WITH PAINT DAMAGE | +DEUK                |              |              |
|     |                          | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 1   | 0 LU =0.00 EUR           | 211.80 EUR                |                      | 50 %         | 211.80 EUR   |

### Interior

|     |               |               |   |                   |              |              |
|-----|---------------|---------------|---|-------------------|--------------|--------------|
| [x] | ARM REST      | CUT / TORN    |   |                   |              |              |
|     | <b>Number</b> | <b>Code</b>   | <b>Description</b>                          | <b>Unit price</b> | <b>Depr.</b> | <b>Total</b> |
| 2   | I 1           | i-vab-intr-01 | LEATHER REPAIR (LENGTH OR DIAMETER MAX 3CM) | 125.04 EUR        |              | 125.04 EUR   |

|     |               |               |                    |                   |              |              |
|-----|---------------|---------------|--------------------|-------------------|--------------|--------------|
| [x] | SEAT REAR L   | STAIN         |                    |                   |              |              |
|     | <b>Number</b> | <b>Code</b>   | <b>Description</b> | <b>Unit price</b> | <b>Depr.</b> | <b>Total</b> |
| 4   | I 1           | i-vab-rein-07 | CLEANING (PER 15') | 14.58 EUR         |              | 14.58 EUR    |

|          |          |          |          |          |          |          |          |          |           |
|----------|----------|----------|----------|----------|----------|----------|----------|----------|-----------|
| <b>1</b> | <b>2</b> | <b>3</b> | <b>4</b> | <b>5</b> | <b>6</b> | <b>7</b> | <b>8</b> | <b>9</b> | <b>10</b> |
| 211.80   | 125.04   | 0        | 14.58    | 0        | 0        | 0        | 0        | 0        | 0         |
| 105.90   | 125.04   | 0        | 14.58    | 0        | 0        | 0        | 0        | 0        | 0         |

|                   |                    |                |                     |
|-------------------|--------------------|----------------|---------------------|
| <b>INNOVATIVE</b> | <b>TRADITIONAL</b> | <b>GENERAL</b> |                     |
| 139.62            | 211.80             | 0              | <b>351.42</b>       |
| HOG: 0            | BG: 0              |                | NA Deprec. 245.52   |
|                   |                    |                | 0.00%               |
|                   |                    |                | <b>TOTAL 245.52</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                           |  |   |
|---------------------------|--|---|
| <b>Extra Time :</b> 0 min | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No  |  |   |
| <b>Reason :</b>           |  |   |
| <b>Remark :</b>           |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 12/10/2017 <b>Hour :</b> 12:21<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br><br>   |                                |