

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	169451 KM
File nr. :	1448200	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EGL246 / W0LGT6EJ4D1034614 /		yr of constructionr :	/
E-File nr. :		First registration :	26/11/2012
VFS-nr. :		Color :	BLUE
Make + Model :	OPEL / INSIGNIA	Fuel type :	DIESEL
Object nr. :	32796	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ARAMARK SA	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	INSIGNIA BER ecofl.Cosmo S/S DPF 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1956
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:			Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/RIGHT/FRONT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE		
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x]	ROOF/FRONT/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR

[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	SLECHTE HERSTELLING		
	Number Code	Description	Unit price	Depr.	Total
0	0				

[x]	LIGHTS/RIGHT/FRONT	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
3	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		29.16 EUR

1	2	3	4	5	6	7	8	9	10
29.16	211.80	24.00	318.35	211.80	0	481.50	0	0	0
29.16	105.90	12.00	159.18	105.90	0	240.75	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
29.16	1247.45	0	1276.61
HOG: 0	BG: 0		NA Deprec. 652.88
			0.00%
			TOTAL 652.88

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 14:24 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	