

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	99931 KM
File nr. :	1450881	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
FK0407 / WDD2052041F174599 /		yr of constructionr :	/
E-File nr. :		First registration :	06/03/2015
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / C BREAK	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	2143
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	170	kW:	125
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :		
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]		
Tax certificate :		Transport licence :		
Fuel card :		Navigation CD/SD/DVD	OK	[x]
Mobile phone kit :		Car radio :	OK	[x]
First aid kit :	OK	[x]	Extinguisher :	OK [x]
Jack, wheelspanner :		Warning triangle :	OK	[x]
		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	Y
Rear tyre	225	50	R	17	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE	+SIERLIJST	
		Repair paint - LI	New paint - E	Depr. Total
1	0 LU =0.00 EUR	211.80 EUR		50 % 211.80 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SIERLIJST	50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
261.80	0	0	0	0	0	0	0	0	0
130.90	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	261.80	0	261.80
HOG: 0	BG: 0		NA Deprec. 130.90
			0.00%
			TOTAL 130.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 08:59 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	