

www.vabfleetservices.be Date: 16/10/2017 1/5

CWG74F

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: VERY DIRTY [x]
Owner:		Mileage:	150396 KM
File nr. :	1446063	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DWC478 / VF1JZ140647743	292 /	yr of constructionr :	/
E-File nr. :		First registration :	14/09/2012
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / SCENIC	Fuel type :	DIESEL
Object nr. :	37802	Fuel :	
Classification:		Environment Class:	EURO 5
Customer company:	KBC VERZEKERINGEN NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering:	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	5 [x]
Vehicle type :	SCENIC Energ.Privilege 110PK	Country registration :	BELGIUM

Variant car:	MONOVOLUME	Engine size:	1461	
Gear box :	Manueel	Number of places:	5	
Number of gears:	6	Number of doors:	5	
нр:	110	kW:	81	
Fisc HP		Imported vehicle:		
Animals transported:		Smoked in vehicle:		
Due date vehicle inspection:		Extra set of tires:		
		Use:	Unknown	
General condition:				

Metallic paint:

Yes



www.vabfleetservices.be Date: 16/10/2017 2/5

Original registr. number : OK Service manual : Cert. of conformity: Cert. of reg. / Part 1: OK Insurance certificate: Cert. of reg. copy / Part 2: OK Warning vest: Transport licence: Tax certificate: Navigation CD/SD/DVD OK Fuel card : Car radio: OK Extinguisher: Mobile phone kit : OK Warning triangle: OK First aid kit : OK Oil level: OK OK Filled up: 0 Jack, wheelspanner :

Wheels and tyres: Summer tires

Wheel FL:	CONTINENTAL	Tyre:	OK	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:
Wheel RL:	CONTINENTAL	Tyre:	OK [x]	2-4 /	Rim:			/	Hubcap:
Wheel FR:	CONTINENTAL	Tyre:	OK	2-4 /	Rim:		WHEEL SCRATCHED	/	Hubcap:
Wheel RR:	CONTINENTAL	Tyre:	OK [x]	2-4 /	Rim:			/	Hubcap:
Wheel RES:		Tyre:	OK	/	Rim:			/	Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	205	55	R	17	V
Rear tyre	205	55	R	17	V

Remark:

Wheels and tyres:

	<u> </u>					
I	Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 16/10/2017 3/5

Conclusion

Bodywork \& windows

[x] FRONT BUMPER/LEFT/SIDE

SCRATCH WITH PAINT DAMAGE

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

[x] REAR MUDGUARD/RIGHT/CENTER DENT

[x] REAR DOOR/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/RIGHT/CENTER DENT

[x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

Interior

[x] SEAT FL CARVED

STATUS: NOT ACCEPTABLE

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

N	lumber	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
190.00	0	0	0	0	0	0	0	0	0
190.00	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
190.00	0	0	190.00
NA Deprec. 190.00		BG: 0	HOG: 0
0.00%			

TOTAL 190.00



www.vabfleetservices.be Date: 16/10/2017 4/5



www.vabfleetservices.be Date: 16/10/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

NORMAL CONCLUSION

CITCOTVI				NORMAL CONCLU	SION	
Extra Time :	0 min	Waiting time :	ng time: 0 min		Towing time :	0 min
		Reason :			Reason:	
NOT EXECUTED	: No					
Reason:						
Remark:						
Prices in EUR	without VAT					
A a				E . 11 WADEL .C		
Authorized by customer:				Executed by VAB Fleet Se	rvices	
Remark authorize	d customer :					
Date :	16/10/2017	Hour: 11:1	1			
Company :						
	Fleet					
Executed by VAB Services	ricet					
E-Mail :	@					
Signature authorized	d by customer					
		\				
		*				