

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	129957 KM
<b>File nr. :</b>	1450394	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DPK637 / VF1JZ00AD47550811 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	13/07/2012
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	RENAULT / GRAND SCENIC	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	KBC BANK NV	<b>Co2:</b>	114g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE-LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	GR.SCENIC Energ.Privilege 5pl.FAP 130PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	
<b>Variant car:</b>		<b>Engine size:</b>	1598
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	131	<b>kW:</b>	96
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :	OK [x]	Car radio :	
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK [x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x] OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK [x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK [x]	>6/	Rim :			/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	17	V
Rear tyre	205	55	R	17	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK /	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK /	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK /	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK /	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	ROOF STYLE/CENTER/RIGHT	DENT	
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/RIGHT/FRONT	DENT	
[x]	FRONT DOOR/LEFT/REAR	DENT	X3
[x]	FRONT DOOR/RIGHT/FRONT	DENT	
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	
[x]	BONNET/CENTER/RIGHT/FRONT	DENT	

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE				
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
7	0 LU	=0.00 EUR	211.80 EUR	50 %	211.80 EUR	
[x]	REAR MUDGUARD/LEFT/FRONT	DENT				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
6	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
6	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR
[x]	ROOF STYLE/CENTER/LEFT	DENT				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
5	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
4	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	FRONT DOOR/LEFT/FRONT	DENT				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] LIGHTS/RIGHT/FRONT

HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
2 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

## Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	CHROOM ROND MISTLICHT	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
0	114.00	63.00	115.56	63.00	82.80	211.80	285.00	0	0
0	57.00	63.00	115.56	63.00	82.80	105.90	285.00	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
609.36	325.80	0	935.16
HOG: 0	BG: 0		NA Deprec. 772.26
			0.00%
			TOTAL 772.26

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 19/10/2017 <b>Hour :</b> 09:02 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	