

CTZV1V

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	127400 KM
File nr. :	1444164	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CAN387 / VF1FLBHB6BY409855 /		yr of constructionr :	/
E-File nr. :		First registration :	05/10/2011
VFS-nr. :		Color :	WHITE
Make + Model :	RENAULT / TRAFIC	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	ASCELEC SPRL	Co2:	195g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	TRAFIC 29 B/F MWB L2H1 Gr.Conf.115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	1995
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	SEMPERIT	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	SEMPERIT	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel FR :	[x]	SEMPERIT	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	SEMPERIT	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	65	R	16	V
Rear tyre	205	65	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE	HERSTELD

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
-----	---------------------------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR	
[x]	ROOF/FRONT/CENTER/RIGHT	DENT				
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	361.13 EUR		50 %	361.13 EUR	
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE				
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 3	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		43.74 EUR

HUB CAP FL

		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR			50 %	

HUB CAP REAR L

		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

1	2	3	4	5	6	7	8	9	10
43.74	110.64	231.15	361.13	67.50	0	0	0	0	0
43.74	110.64	115.58	180.56	33.75	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
154.38	659.78	0	814.16
HOG: 0	BG: 3		NA Deprec. 484.27
			0.00%
			TOTAL 484.27

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 09/10/2017 Hour : 14:12 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	