

D2Q41C

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	103701 KM
File nr. :	1450968	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
LS4401 / JTMDCREV20D055267 /		yr of constructionr :	/
E-File nr. :		First registration :	23/10/2014
VFS-nr. :		Color :	GREY
Make + Model :	TOYOTA / RAV4	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	2231
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK		2-4/	Rim :	[x]	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK		2-4/	Rim :	[x]	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	65	R	17	W
Rear tyre	225	65	R	17	W

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:			Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)		
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE		
[x]	WINDSCREEN/CENTER/LEFT	CHIPS	HERSTELD	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	95.00	0	0	0	0	0	0	0	0
105.90	95.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	211.80	0	306.80
HOG: 0	BG: 0		NA Deprec. 200.90
			0.00%
			TOTAL 200.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 14:46 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	