

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

|                                     |                             |                                 |                               |
|-------------------------------------|-----------------------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING             | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: CLEAN [x] |
| <b>Owner :</b>                      |                             | <b>Mileage :</b>                | 141498 KM                     |
| <b>File nr. :</b>                   | 1450147                     | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                             | <b>Mileag ref. service :</b>    | 0                             |
| 1DUP646 / VF1JZ140647719910 /       |                             | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                             | <b>First registration :</b>     | 03/09/2012                    |
| <b>VFS-nr. :</b>                    |                             | <b>Color :</b>                  | BLACK                         |
| <b>Make + Model :</b>               | RENAULT / SCENIC            | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 | 3779                        | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             |                             | <b>Environment Class:</b>       | EURO 5                        |
| <b>Customer company :</b>           | MEDIAHUIS NV                | <b>Co2:</b>                     | 1461g/km                      |
| <b>Driver :</b>                     |                             | <b>Remote controls:</b>         | 2                             |
| <b>Covering :</b>                   | TISSUE                      | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle kind :</b>               | VEHICLE                     | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               | SCENIC Energ.Business 110PK | <b>Country registration :</b>   | BELGIUM                       |

|                                     |         |                            |         |
|-------------------------------------|---------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   | No      | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 |         | <b>Engine size:</b>        | 1461    |
| <b>Gear box :</b>                   | Manueel | <b>Number of places:</b>   | 5       |
| <b>Number of gears:</b>             | 6       | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 110     | <b>kW:</b>                 | 81      |
| <b>Fisc HP</b>                      |         | <b>Imported vehicle:</b>   |         |
| <b>Animals transported:</b>         |         | <b>Smoked in vehicle:</b>  |         |
| <b>Due date vehicle inspection:</b> |         | <b>Extra set of tires:</b> |         |
|                                     |         | <b>Use:</b>                | Unknown |
| <b>General condition:</b>           |         |                            |         |

|                                     |                           |
|-------------------------------------|---------------------------|
| Original registr. number : OK       | Service manual : OK [x]   |
| Cert. of reg. / Part 1:             | Cert. of conformity : OK  |
| Cert. of reg. copy / Part 2: OK [x] | Insurance certificate :   |
| Warning vest :                      | Transport licence :       |
| Tax certificate :                   | Navigation CD/SD/DVD      |
| Fuel card :                         | Car radio : OK [x]        |
| Mobile phone kit :                  | Extinguisher : OK [x]     |
| First aid kit : OK [x]              | Warning triangle : OK [x] |
| Jack, wheelspanner : OK [x]         | Oil level : OK [x]        |
|                                     | Filled up : 0             |

## Wheels and tyres: Summer tires

|   |
|---|
| Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED      |
| Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED     |
| Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED |
| Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED     |
| Wheel RES: [x] ANDERE Tyre : OK [x] >6/ Rim : / Hubcap :                      |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205   | 60     | R    | 16  | H     |
| Rear tyre  | 205   | 60     | R    | 16  | H     |

Remark :

## Wheels and tyres:

|   |
|---|
| Wheel FL: Tyre : OK / Rim : / Hubcap :  |
| Wheel RL : Tyre : OK / Rim : / Hubcap : |
| Wheel FR : Tyre : OK / Rim : / Hubcap : |
| Wheel RR : Tyre : OK / Rim : / Hubcap : |
| Wheel RES: Tyre : OK / Rim : / Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE
- [x] FRONT DOOR/LEFT/CENTER DENT
- [x] FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                           |                          |                           |              |                     |  |
|-----|---------------------------|--------------------------|---------------------------|--------------|---------------------|--|
| [x] | REAR DOOR/CENTER/LEFT     |                          | DENT                      |              |                     |  |
|     |                           | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b>        |  |
| 4   | 20 LU =96.00 EUR          | 301.68 EUR               |                           | 50 %         | 397.68 EUR          |  |
| [x] | REAR BUMPER/RIGHT/CORNER  |                          | SCRATCH WITH PAINT DAMAGE |              |                     |  |
|     |                           | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b>        |  |
| 5   | 0 LU =0.00 EUR            | 211.80 EUR               |                           | 50 %         | 211.80 EUR          |  |
| [x] | REAR MUDGUARD/LEFT/CENTER |                          | SCRATCH WITH PAINT DAMAGE |              |                     |  |
|     |                           | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b>        |  |
| 3   | 0 LU =0.00 EUR            | 308.20 EUR               |                           | 50 %         | 308.20 EUR          |  |
| [x] | REAR MUDGUARD/RIGHT/FRONT |                          | SCRATCH WITH PAINT DAMAGE |              |                     |  |
|     |                           | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b>        |  |
| 6   | 0 LU =0.00 EUR            | 308.20 EUR               |                           | 50 %         | 308.20 EUR          |  |
| [x] | REAR DOOR/LEFT/CENTER     |                          | SCRATCH WITH PAINT DAMAGE |              |                     |  |
|     |                           | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b>        |  |
| 3   | 0 LU =0.00 EUR            | 318.35 EUR               |                           | 50 %         | 318.35 EUR          |  |
| [x] | ROOF/CENTER/RIGHT         |                          | OTHER DAMAGES             |              | CHEMISCHE INWERKING |  |
|     |                           | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b>        |  |
| 7   | 0 LU =0.00 EUR            | 481.50 EUR               |                           | 50 %         | 481.50 EUR          |  |
| [x] | REAR DOOR/RIGHT/CENTER    |                          | SCRATCH WITH PAINT DAMAGE |              |                     |  |
|     |                           | <b>Repair paint - LI</b> | <b>New paint - E</b>      | <b>Depr.</b> | <b>Total</b>        |  |
| 6   | 0 LU =0.00 EUR            | 318.35 EUR               |                           | 50 %         | 318.35 EUR          |  |

|     |                       |                           |                      |              |              |
|-----|-----------------------|---------------------------|----------------------|--------------|--------------|
| [x] | FRONT DOOR/RIGHT/REAR | SCRATCH WITH PAINT DAMAGE |                      |              |              |
|     |                       | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 6   | 0 LU =0.00 EUR        | 318.35 EUR                |                      | 50 %         | 318.35 EUR   |

|     |                           |                           |                      |              |              |
|-----|---------------------------|---------------------------|----------------------|--------------|--------------|
| [x] | FRONT MUDGUARD/LEFT/Front | SCRATCH WITH PAINT DAMAGE |                      |              |              |
|     |                           | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 2   | 0 LU =0.00 EUR            | 220.18 EUR                |                      | 50 %         | 220.18 EUR   |

|     |                    |                           |                      |              |              |
|-----|--------------------|---------------------------|----------------------|--------------|--------------|
| [x] | BONNET/LEFT/CENTER | SCRATCH WITH PAINT DAMAGE |                      |              |              |
|     |                    | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 1   | 0 LU =0.00 EUR     | 290.08 EUR                |                      |              | 290.08 EUR   |

### Accessories and others

|     |                               |                           |                      |              |              |
|-----|-------------------------------|---------------------------|----------------------|--------------|--------------|
| [x] | OUTSIDE MIRROR RIGHTHAND SIDE | SCRATCH WITH PAINT DAMAGE |                      |              |              |
|     |                               | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 6   | 11 i-vab-sp-01                | SPOTREPAIR                |                      | 115.56 EUR   | 115.56 EUR   |

### Others

HUB CAP FL

|   |                |                          |                      |              |              |
|---|----------------|--------------------------|----------------------|--------------|--------------|
|   |                | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 8 | 0 LU =0.00 EUR |                          |                      | 50 %         |              |

HUB CAP FR

|   |                |                          |                      |              |              |
|---|----------------|--------------------------|----------------------|--------------|--------------|
|   |                | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 8 | 0 LU =0.00 EUR |                          |                      | 50 %         |              |

### Pieces

|   |               |             |                    |                   |              |              |
|---|---------------|-------------|--------------------|-------------------|--------------|--------------|
|   | <b>Number</b> | <b>Code</b> | <b>Description</b> | <b>Unit price</b> | <b>Depr.</b> | <b>Total</b> |
| 8 | 1             | WHEEL CAP   |                    | 30.00 EUR         | 50 %         | 30.00 EUR    |

|   |               |             |                    |                   |              |              |
|---|---------------|-------------|--------------------|-------------------|--------------|--------------|
|   | <b>Number</b> | <b>Code</b> | <b>Description</b> | <b>Unit price</b> | <b>Depr.</b> | <b>Total</b> |
| 8 | 1             | WHEEL CAP   |                    | 30.00 EUR         | 50 %         | 30.00 EUR    |

|          |          |          |          |          |          |          |          |          |           |
|----------|----------|----------|----------|----------|----------|----------|----------|----------|-----------|
| <b>1</b> | <b>2</b> | <b>3</b> | <b>4</b> | <b>5</b> | <b>6</b> | <b>7</b> | <b>8</b> | <b>9</b> | <b>10</b> |
| 290.08   | 220.18   | 626.55   | 397.68   | 211.80   | 1060.46  | 481.50   | 60.00    | 0        | 0         |
| 290.08   | 110.09   | 313.28   | 198.84   | 105.90   | 588.01   | 240.75   | 30.00    | 0        | 0         |

| INNOVATIVE | TRADITIONAL | GENERAL |                      |
|------------|-------------|---------|----------------------|
| 115.56     | 3232.69     | 0       | <b>3348.25</b>       |
| HOG: 0     | BG: 0       |         | NA Deprec. 1876.94   |
|            |             |         | 0.00%                |
|            |             |         | <b>TOTAL 1876.94</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|   |  |   |
|---|--|---|
| <b>Extra Time :</b> 0 min                   | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No<br><b>Reason :</b> |  |   |
| <b>Remark :</b>                             |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 18/10/2017 <b>Hour :</b> 15:24<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>   |                                |