

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	38655 KM
File nr. :	1447684	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ALY067 / VF1FW1BH544737948 /		yr of constructionr :	/
E-File nr. :		First registration :	07/02/2011
VFS-nr. :		Color :	WHITE
Make + Model :	RENAULT / KANGOO EXPRESS	Fuel type :	DIESEL
Object nr. :	47822	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	DALKIA SA<ID>2229924</ID>	Co2:	140g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	KANGOO EXPR.B/F MAXI Grand Confort 86PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1461
Gear box :	Manueel	Number of places:	2
Number of gears:	5	Number of doors:	5
HP:	86	kW:	63
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/CENTER/LEFT	DENT
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	ROOF/CENTER/RIGHT	DENT

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
-----	---------------------------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT BUMPER/CENTER/LEFT	HOLE/CRACK/TORN				
			Repair paint - LI	New paint - E	Depr.	Total
1	20 LU =96.00 EUR	0 EUR			50 %	96.00 EUR

Interior

[x]	FLOOR FL	HOLE				
			Repair paint - LI	New paint - E	Depr.	Total
2	40 LU =192.00 EUR	0 EUR			50 %	192.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	RUBBER MAT	40.00 EUR	50 %	40.00 EUR

1	2	3	4	5	6	7	8	9	10
398.40	232.00	0	0	0	0	0	0	0	0
199.20	116.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	630.40	0	630.40
HOG: 0	BG: 3		NA Deprec. 315.20
			0.00%
			TOTAL 315.20

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 13:34 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	