

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	158942 KM
File nr. :	1448311	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EAK181 / VF1JZ09A347850284 /		yr of constructionr :	/
E-File nr. :		First registration :	03/10/2012
VFS-nr. :		Color :	BLACK
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :	38516	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SATIC NV	Co2:	124g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	5 [x]
Vehicle type :	GR.SCENIC Privilege 5pl.FAP 110PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] KLÉBER Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] KLÉBER Tyre : [x] OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] KLÉBER Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	17	V
Rear tyre	205	55	R	17	V

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT
[x]	REAR DOOR/LEFT/CENTER	DENT
[x]	REAR DOOR/RIGHT/CENTER	DENT
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0
			0.00%
			TOTAL 0

