

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: VERY DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	183879 KM
File nr. :	1450941	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
AT7811 / WVWZZZ6RZDY278927 /		yr of constructionr :	/
E-File nr. :		First registration :	26/06/2013
VFS-nr. :		Color :	BLUE
Make + Model :	VOLKSWAGEN / POLO	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	COSTANTINI SA	Co2:	g/km
Driver :		Remote controls:	
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	POLO BER Trendline DPF 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :		
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	175	70	R	14	T
Rear tyre	175	70	R	14	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
5	15 LU =72.00 EUR		169.44 EUR		50 %
					241.44 EUR
[x]	FRONT DOOR/LEFT/REAR	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
4	15 LU =72.00 EUR		254.68 EUR		50 %
					326.68 EUR
[x]	BONNET/CENTER/RIGHT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
2	45 LU =216.00 EUR		232.06 EUR		50 %
					448.06 EUR
[x]	FRONT BUMPER/CENTER/LEFT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
3	10 LU =48.00 EUR		169.44 EUR		50 %
					217.44 EUR

Interior

[x]	SEAT REAR L	BURNT			
			Repair paint - LI	New paint - E	Depr.
					Total
1	0 LU =0.00 EUR		0 EUR		50 %
			Repair paint - LI	New paint - E	Depr.
					Total
1	25 LU =120.00 EUR		0 EUR		50 %
					120.00 EUR
[x]	SEAT REAR RIGHT	OTHER DAMAGES			
			Unit price	Depr.	Total
1	I 3 i-vab-ander-01	REPAIR (PER 15')	18.74 EUR		56.22 EUR

[x] BACK SHELF

CUT / TORN

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	0 EUR		50 %	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 8	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	91.76 EUR

CLEANLINESS EXTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	personenwagen-a-vab-reex-02	CLEANING EXTERIOR	11.47 EUR	11.47 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SEAT UPHOLSTERY TISSUE	96.00 EUR	50 %	96.00 EUR

Number	Code	Description	Unit price	Depr.	Total
1	1	BACK SHELF	40.00 EUR	50 %	40.00 EUR

1	2	3	4	5	6	7	8	9	10
415.45	448.06	217.44	326.68	241.44	0	0	0	0	0
287.45	224.03	108.72	163.34	120.72	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
159.45	1489.62	0	1649.07
HOG: 0	BG: 1		NA Deprec. 904.26
			0.00%
			TOTAL 904.26

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 09:54 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	