

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	171709 KM
File nr. :	1446180	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HTK575 / WVWZZZ3CZFE043483 /		yr of constructionr :	/
E-File nr. :		First registration :	29/09/2014
VFS-nr. :		Color :	BLUE D
Make + Model :	VOLKSWAGEN / PASSAT BREAK	Fuel type :	DIESEL
Object nr. :	62334	Fuel :	
Classification :	C	Environment Class:	EURO 5
Customer company :	INOVYN MANUFACTURING JEMEPPE	Co2:	120g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	OK
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	BRIDGESTONE	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RL :	DUNLOP	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel FR :	BRIDGESTONE	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RR :	DUNLOP	Tyre :	OK	2-4/	Rim :	/	Hubcap :
Wheel RES:	ANDERE	Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/RIGHT	DENT		
[x]	FRONT THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	INTERIEUR	
	BONNET/CENTER/LEFT/FRONT	CHIPS		
	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	DENT		
-----	-----------------------	------	--	--

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR

[x]	BONNET/CENTER/RIGHT/FRONT	DENT		
-----	---------------------------	------	--	--

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	82.80	0	0	0	0	0	0	0	0
63.00	82.80	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
145.80	0	0	145.80
HOG: 0	BG: 0		NA Deprec. 145.80
			0.00%
			TOTAL 145.80

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 14:33 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	