

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	147985 KM
File nr. :	1446614	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DFS614 / WVWZZZ3CZCE175057 /		yr of constructionr :	/
E-File nr. :		First registration :	07/05/2012
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / PASSAT BREAK	Fuel type :	DIESEL
Object nr. :	11905	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SIMAC NV	Co2:	116g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PASSAT VAR Comfortline 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT BUMPER/LEFT/SIDE SCRATCH (WITHOUT PAINT DAMAGE) POLIEREN

Interior

[x] SEAT FL OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR WINDOW/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	0 EUR		50 %	
1 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

Interior

[x] FLOOR BOOT DIRTY

Number	Code	Description	Unit price	Depr.	Total
3	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	14.58 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
370.00	211.80	14.58	0	0	0	0	0	0	0
185.00	105.90	14.58	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
14.58	581.80	0	596.38
HOG: 0	BG: 0		NA Deprec. 305.48
			0.00%
			TOTAL 305.48

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 09:00 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	