

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	182446 KM
File nr. :	1450885	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
DJ8864 / WVWZZZ3CZEE132772 /		yr of constructionr :	/
E-File nr. :		First registration :	27/05/2014
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / PASSAT	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	C	Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :		
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK
Jack, wheelspanner :	OK	[x]	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]	PIRELLI	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS
[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
-----	---------------------------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
3	10 LU =48.00 EUR	0 EUR	235.80 EUR	50 %	283.80 EUR
[x]	REAR DOOR/CENTER/LEFT	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	0 EUR		50 %	
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE			
	Number Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
	Number Code	Description	Unit price	Depr.	Total
5	I 2 i-vab-herstr-02	SUPL WINDOW REPAIR	29.40 EUR		58.80 EUR
[x]	FRONT BUMPER/CENTER/LEFT	OTHER DAMAGES		SENSOR	
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
2	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Interior

[x] SEAT FL SCRATCHED

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intlr-01	LEATHER REPAIR (LENGTH OR DIAMETER MAX 3CM)	125.04 EUR	125.04 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	11.47 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	SENSOR	75.00 EUR	50 %	75.00 EUR

Number	Code	Description	Unit price	Depr.	Total
3	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR

Number	Code	Description	Unit price	Depr.	Total
4	1	EMBLEEM	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
136.51	99.00	627.00	30.00	117.60	0	0	0	0	0
136.51	49.50	313.50	15.00	117.60	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
254.11	756.00	0	1010.11
HOG: 0	BG: 0		NA Deprec. 632.11
			0.00%
			TOTAL 632.11

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 09:18 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	