

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	34723 KM
<b>File nr. :</b>	1447903	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1LDR349 / WVVZZZAUZFP102954 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	31/08/2015
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	VOLKSWAGEN / GOLF	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	59063	<b>Fuel :</b>	
<b>Classification :</b>	E	<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	VAB RIJSCHOOL NV	<b>Co2:</b>	102g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1598
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	105	<b>kW:</b>	77
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL: [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] CONTINENTAL Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] MISSING/INCOMPLETE
Wheel RR : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] CONTINENTAL Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

## Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		DENT					
				<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR			211.80 EUR			50 %	211.80 EUR
[x]	REAR DOOR/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE					
				<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR			318.35 EUR			50 %	318.35 EUR
[x]	FRONT DOOR/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE					
				<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
4	0 LU =0.00 EUR			318.35 EUR			50 %	318.35 EUR
[x]	FRONT DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE					
				<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR			318.35 EUR			50 %	318.35 EUR
[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE					
				<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR			211.80 EUR			50 %	211.80 EUR

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		14.58 EUR

HUB CAP FR

			<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
6	0 LU =0.00 EUR					50 %	

### Pieces

Number	Code	Description	Unit price	Depr.	Total
6	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	636.70	211.80	318.35	211.80	30.00	0	0	0	0
14.58	318.35	105.90	159.18	105.90	15.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
14.58	1408.65	0	<b>1423.23</b>
HOG: 0	BG: 0		NA Deprec. 718.90
			0.00%
			<b>TOTAL 718.90</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

## Prices in EUR without VAT

Authorized by customer :  Remark authorized customer :  Date : 17/10/2017      Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	