

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	170626 KM
File nr. :	1447266	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
YD4299 / WVVZZZAUZFW524127 /		yr of constructionr :	/
E-File nr. :		First registration :	27/08/2014
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / GOLF PLUS	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	E	Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :		
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]		
Tax certificate :		Transport licence :		
Fuel card :		Navigation CD/SD/DVD	[x]	
Mobile phone kit :		Car radio :	OK	[x]
		Extinguisher :	OK	[x]
First aid kit :	OK	[x]		
		Warning triangle :	OK	[x]
Jack, wheelspanner :	OK	[x]		
		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	DESCRIPTION	DAMAGE	REPAIR	DEPR.	TOTAL
	BONNET/CENTER/RIGHT/FRONT	DENT		+LAKSCHADE	
			Repair paint - LI	New paint - E	Depr.
3	0 LU =0.00 EUR		290.08 EUR	50 %	290.08 EUR
	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
1	0 LU =0.00 EUR		211.80 EUR	50 %	211.80 EUR
	ROOF/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
2	0 LU =0.00 EUR		481.50 EUR	50 %	481.50 EUR

1	2	3	4	5	6	7	8	9	10
211.80	481.50	290.08	0	0	0	0	0	0	0
105.90	240.75	145.04	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	983.38	0	983.38
HOG: 0	BG: 0		NA Deprec. 491.69
			0.00%
			TOTAL 491.69

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : DOCUMENTEN WORDEN NAGESTUURD [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 12:05 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	