

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	147556 KM
File nr. :	1450156	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EBM065 / WVWZZZ7NZDV011236 /		yr of constructionr :	/
E-File nr. :		First registration :	11/10/2012
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / SHARAN	Fuel type :	DIESEL
Object nr. :	703327	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	INDICATOR NV	Co2:	146g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	SHARAN Comfortline 140PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1968
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	140	kW:	103
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	FULDA	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	FULDA	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	FULDA	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	FULDA	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]	FULDA	Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	M+S
Rear tyre	215	60	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	ROOF STYLE/CENTER/LEFT	DENT
[x]	REAR DOOR/RIGHT/FRONT	DENT
[x]	ROOF STYLE/FRONT/LEFT/CENTER	DENT
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	WINDSCREEN/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
-----	-------------------------	---------------------------

	Repair paint - LI	New paint - E	Depr.	Total
1 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WIND SCREEN	440.64 EUR	50 %	440.64 EUR

1	2	3	4	5	6	7	8	9	10
560.64	0	0	0	0	0	0	0	0	0
280.32	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	560.64	0	560.64
HOG: 0	BG: 2		NA Deprec. 280.32
			0.00%
			TOTAL 280.32

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 15:50 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	