

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	34385 KM
File nr. :	1447747	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LNP440 / WVWZZZ3CZGE103722 /		yr of constructionr :	/
E-File nr. :		First registration :	29/10/2015
VFS-nr. :		Color :	BLUE
Make + Model :	VOLKSWAGEN / PASSAT	Fuel type :	DIESEL
Object nr. :	76232	Fuel :	
Classification :	C	Environment Class:	EURO 6
Customer company :	TECH MAHINDRA LTD	Co2:	107g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	120	kW:	88
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :		
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	ANDERE	Tyre :	OK	[x]	0-1.6/	Rim :	/	Hubcap :		
Wheel RL :	[x]	ANDERE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel FR :	[x]	ANDERE	Tyre :	[x]	OK	[x]	0-1.6/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	ANDERE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	V
Rear tyre	215	60	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/FRONT DENT
- [x] REAR DOOR/LEFT/FRONT DENT
- [x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

- [x] REAR DOOR/RIGHT/RIGHT DENT

Number	Code	Description	Unit price	Depr.	Total
6	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

- [x] BONNET/CENTER/RIGHT/FRONT OTHER DAMAGES CHEMISCHE+ DEUKEN

	Repair paint - LI	New paint - E	Depr.	Total
3 10 LU =48.00 EUR	290.08 EUR		50 %	338.08 EUR

- [x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

- [x] ROOF/CENTER/LEFT OTHER DAMAGES CHEMISCHE + DEUKEN

	Repair paint - LI	New paint - E	Depr.	Total
4 10 LU =48.00 EUR	481.50 EUR		50 %	529.50 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1 personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR		11.47 EUR

1	2	3	4	5	6	7	8	9	10
11.47	211.80	338.08	529.50	211.80	63.00	0	0	0	0
11.47	105.90	169.04	264.75	105.90	63.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
74.47	1291.18	0	1365.65
HOG: 0	BG: 0		NA Deprec. 720.06
			0.00%
			TOTAL 720.06

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 09:12 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	