

D13IRK

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	124818 KM
File nr. :	1449674	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EDW620 / WVGZZZ1TZDW040054 /		yr of constructionr :	/
E-File nr. :		First registration :	02/11/2012
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / TOURAN	Fuel type :	DIESEL
Object nr. :	51411	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CEGEKA NV	Co2:	121g/km
Driver :		Remote controls:	2
Covering :	TISSUE-ALCANTARA	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	TOURAN Highline BMT Start/Stop 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	UNIROYAL	Tyre :	OK	4-6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	UNIROYAL	Tyre :	OK	4-6/	Rim :		/	Hubcap :
Wheel FR :	UNIROYAL	Tyre :	OK	4-6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	UNIROYAL	Tyre :	OK	4-6/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark : REPSET OK

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] WINDSCREEN/CENTER/LEFT CHIPS
- [x] BONNET/CENTER/LEFT/FRONT CHIPS
- [x] FRONT BUMPER/CENTER/LEFT CHIPS

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 0		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 11:42 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	