

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	42503 KM
File nr. :	1447870	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1LHB385 / WVVZZZAUF310931 /		yr of constructionr :	/
E-File nr. :		First registration :	28/09/2015
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	59063	Fuel :	
Classification :	E	Environment Class:	EURO 5
Customer company :	VAB RIJSCHOOL NV	Co2:	98g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] CONTINENTAL Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RR : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] CONTINENTAL Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	14.58 EUR

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	30.00	0	0	0	0	0	0	0	0
14.58	15.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
14.58	30.00	0	44.58
HOG: 0	BG: 0		NA Deprec. 29.58
			0.00%
			TOTAL 29.58

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	