

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	200825 KM
File nr. :	1449025	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FBT887 / YV1DZ31A1D2463848 /		yr of constructionr :	/
E-File nr. :		First registration :	17/05/2013
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / XC60	Fuel type :	DIESEL
Object nr. :	54086	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	TAMINCO BVBA	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	XC60 D3 Kinetic Start/Stop 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1984
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	60	R	17	M+S
Rear tyre	235	60	R	17	M+S

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/FRONT DENT

[x] BONNET/CENTER/RIGHT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/LEFT/REAR	OTHER DAMAGES	INWERKING		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x]	REAR DOOR/RIGHT/CENTER	DENT				
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x]	FRONT BUMPER/RIGHT/CORNER	DENT				
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

1	2	3	4	5	6	7	8	9	10
226.20	63.00	318.35	0	0	0	0	0	0	0
226.20	63.00	159.18	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
289.20	318.35	0	607.55
HOG: 0	BG: 0		NA Deprec. 448.38
			0.00%
			TOTAL 448.38

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/10/2017 Hour : 11:29 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	