

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	142851 KM
File nr. :	1444733	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FCM346 / YV1FW84A1D1135051 /		yr of constructionr :	/
E-File nr. :		First registration :	24/05/2013
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / V60	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V60 D2 Kinetic St/St 115PK	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:	24/05/2018	Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE	L/R CHARGEMENT
[x]	REAR DOOR/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE	POLIR
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT	
[x]	REAR DOOR/RIGHT/REAR	CHIPS	BOORD DEUR
[x]	FRONT THRESHOLD/LEFT/REAR	DENT	BIN DEUR/DREMPEL
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	BOORD DEUR
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	BOORD DEUR
[x]	FRONT DOOR/RIGHT/CENTER	DENT	
[x]	FRONT DOOR/RIGHT/FRONT	DENT	
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	ISOLATIE
[x]	FRONT WHEEL/RIGHT	OTHER DAMAGES	COQUILLE/REGALGE

Interior

[x]	CENTER CONSOLE	CARVED
[x]	DOOR IN FL	CARVED
[x]	DOOR IN FR	CARVED
[x]	DOOR IN REAR L	CARVED
[x]	BOOT IN L	SCRATCHED
[x]	BOOT IN R	SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT
-----	--------------------------	------

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR

[x] FRONT BUMPER/RIGHT/SIDE DENT

Number	Code	Description	Unit price	Depr.	Total
2	I1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

1	2	3	4	5	6	7	8	9	10
63.00	115.56	0	0	0	0	0	0	0	0
63.00	115.56	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
178.56	0	0	178.56
HOG: 0	BG: 0		NA Deprec. 178.56
			0.00%
			TOTAL 178.56

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 04/10/2017 Hour : 12:50 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	