

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|----------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 203707 KM |
| File nr. : | 1445110 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FH0826 / YV1DZ88A1E2512631 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 01/07/2013 |
| VFS-nr. : | | Color : | BROWN |
| Make + Model : | VOLVO / XC60 | Fuel type : | DIESEL |
| Object nr. : | 49793 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | VORMINGSFONDS UITZENDKRACHTEN | Co2: | 139g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | XC60 D4 Kinetic 163PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | SUV | Engine size: | 1984 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 163 | kW: | 120 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | OK [x] |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | |
|------------|-----|---------|--------|-----|-----|------|-------|-------|--------------------------------|
| Wheel FL: | [x] | PIRELLI | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RL : | [x] | PIRELLI | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : |
| Wheel FR : | [x] | PIRELLI | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RR : | [x] | PIRELLI | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 235 | 60 | R | 18 | V |
| Rear tyre | 235 | 60 | R | 18 | V |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

Conclusion

Bodywork \& windows

[x] BONNET/CENTER/LEFT/FRONT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | Repair paint - LI | New paint - E | Depr. | Total |
|-----------------------------|-------------------|---------------|-------|------------|
| [x] REAR DOOR/RIGHT/CENTER | | | | |
| | | | | |
| | | | | |
| 3 0 LU =0.00 EUR | 318.35 EUR | | 50 % | 318.35 EUR |
| [x] BONNET/CENTER/LEFT | | | | |
| | | | | |
| | | | | |
| 2 0 LU =0.00 EUR | 290.08 EUR | | 50 % | 290.08 EUR |
| [x] FRONT BUMPER/RIGHT/SIDE | | | | |
| | | | | |
| | | | | |
| 4 0 LU =0.00 EUR | 211.80 EUR | | 50 % | 211.80 EUR |

Others

RIM FRONT RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 1 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|--------|--------|--------|---|---|---|---|---|----|
| 95.00 | 290.08 | 318.35 | 211.80 | 0 | 0 | 0 | 0 | 0 | 0 |
| 95.00 | 145.04 | 159.18 | 105.90 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|-------------------|
| 95.00 | 820.23 | 0 | 915.23 |
| HOG: 0 | BG: 0 | | NA Deprec. 505.12 |
| | | | 0.00% |
| | | | TOTAL 505.12 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 10:59 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |