

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	112805 KM
File nr. :	1446378	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPZ458 / YV1DZ31A1E2536745 /		yr of constructionr :	/
E-File nr. :		First registration :	19/09/2013
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / XC60	Fuel type :	DIESEL
Object nr. :	44789	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SIRRIS VZW ASBL	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	XC60 D3 Kinetic 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1984
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	[x]	
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	65	R	17	V
Rear tyre	225	65	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR WINDOW/LEFT	OTHER DAMAGES	LICHTE KRASSEN IJSKRABBER
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT	
[x]	WINDSCREEN/CENTER/RIGHT	CHIPS	
[x]	FRONT DOOR/RIGHT/CENTER	DENT	
[x]	REAR DOOR/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	ROOF/FRONT/CENTER/RIGHT	OTHER DAMAGES	INWERKING LAK		
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR
[x]	BONNET/CENTER/RIGHT/FRONT	OTHER DAMAGES	INWERKING LAK		
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

1	2	3	4	5	6	7	8	9	10
771.58	0	0	0	0	0	0	0	0	0
385.79	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	771.58	0	771.58
HOG: 0	BG: 0		NA Deprec. 385.79
			0.00%
			TOTAL 385.79

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 09:07 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	