

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	172873 KM
File nr. :	1447727	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GMK931 / WAUZZZ8K1EA092211 /		yr of constructionr :	/
E-File nr. :		First registration :	11/03/2014
VFS-nr. :		Color :	BROWN
Make + Model :	AUDI / A4 AVANT	Fuel type :	DIESEL
Object nr. :	8300	Fuel :	
Classification :	F	Environment Class:	EURO 5
Customer company :	TOMRA SORTING NV	Co2:	124g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:	Yes	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	[x]	
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	245	40	R	18	Y
Rear tyre	245	40	R	18	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT BUMPER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	190.00	0	0	0	0	0	0	0	0
105.90	190.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	211.80	0	401.80
HOG: 0	BG: 0		NA Deprec. 295.90
			0.00%
			TOTAL 295.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 09:58 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	