

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	77350 KM
File nr. :	1448103	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FCM363 / VF34H9HP0DS059644 /		yr of constructionr :	/
E-File nr. :		First registration :	24/05/2013
VFS-nr. :		Color :	SILVER
Make + Model :	PEUGEOT / 308 BREAK	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	119g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	308 SW Active 92PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	92	kW:	68
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK [x]	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	VREDESTEIN	Tyre :	OK	[x]	4-6/	Rim :	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	VREDESTEIN	Tyre :	OK		2-4/	Rim :		/	Hubcap :	
Wheel FR :	[x]	VREDESTEIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	VREDESTEIN	Tyre :	OK		2-4/	Rim :		/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE		
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT		
[x]	REAR THRESHOLD/LEFT/REAR	DENT	INT	
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	RAND	
[x]	FRONT DOOR/LEFT/CENTER	DENT		

Interior

[x]	SEAT REAR RIGHT	STAIN		
[x]	DOOR IN FR	SCRATCHED		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR MUDGUARD/RIGHT/REAR	DENT				
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Others

RIM FRONT RIGHT

	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	63.00	95.00	0	0	0	0	0	0	0
63.00	63.00	95.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
221.00	0	0	221.00
HOG: 0	BG: 0		NA Deprec. 221.00
			0.00%
			TOTAL 221.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 12:53 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	