

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	144111 KM
File nr. :	1445815	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HNU910 / WVVZZZAUZFW080495 /		yr of constructionr :	/
E-File nr. :		First registration :	01/09/2014
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	59949	Fuel :	
Classification :	E	Environment Class:	EURO 5
Customer company :	AVERTIM	Co2:	99g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :		
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	FIRESTONE	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :	
Wheel FR :	[x]	FIRESTONE	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	[x]	>6/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT MUDGUARD/RIGHT/CENTER	DENT
[x]	BONNET/CENTER/RIGHT/FRONT	DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
		Total		
3	0 LU =0.00 EUR	211.80 EUR		50 %
				211.80 EUR
[x]	REAR DOOR/CENTER/RIGHT	DENT		MEERDERE
		Repair paint - LI	New paint - E	Depr.
		Total		
4	10 LU =48.00 EUR	301.68 EUR		50 %
				349.68 EUR
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
		Total		
5	0 LU =0.00 EUR	318.35 EUR		50 %
				318.35 EUR
[x]	FRONT BUMPER/RIGHT	HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.
		Total		
2	20 LU =96.00 EUR	0 EUR	235.80 EUR	50 %
				331.80 EUR

Interior

[x]	BOOT LID IN	CARVED		
		Repair paint - LI	New paint - E	Depr.
		Total		
1	5 LU =24.00 EUR	0 EUR		50 %
				24.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	45.88 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	UPHOLSTERY DOOR	90.00 EUR	50 %	90.00 EUR

Number	Code	Description	Unit price	Depr.	Total
2	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR

1	2	3	4	5	6	7	8	9	10
159.88	735.00	211.80	349.68	318.35	95.00	0	0	0	0
102.88	367.50	105.90	174.84	159.18	95.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
140.88	1728.83	0	1869.71
HOG: 0	BG: 0		NA Deprec. 1005.30
			0.00%
			TOTAL 1005.30

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 13:51 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	