

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	127206 KM
File nr. :	1447158	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DAP249 / YV1MS84F1C2578631 /		yr of constructionr :	/
E-File nr. :		First registration :	27/03/2012
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / S40	Fuel type :	DIESEL
Object nr. :	36740	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	TECH DATA NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	S40 BER DRIVe Start/Stop 99g 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BERLINE	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT		
[x]	ROOF/REAR/LEFT	DENT		
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE	CHEMISCHE	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
		Total		
3	0 LU =0.00 EUR	211.80 EUR		50 %
				211.80 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	OTHER DAMAGES		SLECHT HERSTELD
	Number	Code	Description	Unit price
	Depr.	Total		
0	0			
[x]	BONNET/CENTER/LEFT/FRONT	OTHER DAMAGES		CHEMISCHE
		Repair paint - LI	New paint - E	Depr.
		Total		
2	0 LU =0.00 EUR	290.08 EUR		50 %
				290.08 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	BROKEN / CRACKED		
		Repair paint - LI	New paint - E	Depr.
		Total		
4	5 LU =24.00 EUR	0 EUR		50 %
				24.00 EUR
[x]	OUTSIDE MIRROR RIGHTHAND SIDE	BROKEN / CRACKED		
		Repair paint - LI	New paint - E	Depr.
		Total		
5	5 LU =24.00 EUR	0 EUR		50 %
				24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	KAPJE TREKOOG	20.00 EUR	50 %	20.00 EUR
4	1	SIDE INDICATOR	6.00 EUR	50 %	6.00 EUR
5	1	SIDE INDICATOR	6.00 EUR	50 %	6.00 EUR

1	2	3	4	5	6	7	8	9	10
0	290.08	231.80	30.00	30.00	0	0	0	0	0
0	145.04	115.90	15.00	15.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	581.88	0	581.88
HOG: 0	BG: 0		NA Deprec. 290.94
			0.00%
			TOTAL 290.94

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 10:01 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	