

CZ37MM

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	182260 KM
File nr. :	1448090	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HVX227 / WVVZZZAUZFP033031 /		yr of constructionr :	/
E-File nr. :		First registration :	16/10/2014
VFS-nr. :		Color :	SILVER
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	40143	Fuel :	
Classification :	E	Environment Class:	EURO 5
Customer company :	BELEMCO NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :
	[x]								[x] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	M+S
Rear tyre	195	65	R	15	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	WINDSCREEN/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	FRONT DOOR/LEFT/FRONT	DENT		LAKSCHADE	
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		58.32 EUR

1	2	3	4	5	6	7	8	9	10
58.32	211.80	318.35	308.20	0	0	0	0	0	0
58.32	105.90	159.18	154.10	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.32	838.35	0	896.67
HOG: 0	BG: 0		NA Deprec. 477.50
			0.00%
			TOTAL 477.50

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/10/2017 Hour : 12:31 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	