

www.vabfleetservices.be Date: 13/10/2017 1/5

CVT7YK

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 178325 KM File nr. : Mileage start / arrival: 0 / 01445592 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DWT802 / YV1FS84A1D2191088 / E-File nr. : First registration: 20/09/2012 VFS-nr.: Color: **GREY** Make + Model : Fuel type : VOLVO / S60 **DIESEL** Object nr. : Fuel: **Environment Class:** Classification: EURO 5 Customer company: Co2: ACERTA SOC. 114g/km VERZEKERINGSFONDS VZW Driver: Remote controls: 2 Number keys : Covering: TISSUE 2[x]Vehicle kind: Seats (minivan): Vehicle type: S60 BER D2 Kinetic St/St 115PK Country registration: **BELGIUM**

Variant car:	BERLINE	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	_	<u> </u>	

Metallic paint:

Yes



13/10/2017 Date: www.vabfleetservices.be 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:		[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MIC	HELIN	Tyre:		OK	[x]	1.6-2 /	Rim:			,	Hubcap :	
Wheel RL:	[x]	MIC	HELIN	Tyre:		OK	[x]	4-6 /	Rim:			,	Hubcap:	
Wheel FR:	[x]	MIC	HELIN	Tyre:	[x]	OK	[x]	1.6-2 /	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:	
Wheel RR:	[x]	MIC	HELIN	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:	
Wheel RES:	[x]	AND	DERE	Tyre:		OK		/	Rim:			,	Hubcap:	
		_												
		[x]		Width			Н	eight			Type		Rim	Index
Front tyre				205				60			R		16	V

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	205	60	R	16	V
	Rear tyre	205	60	R	16	V
_						

REP. KIT OK Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



1 I 1 i-vab-intvnl-01

APPRAISAL

13/10/2017 Date: www.vabfleetservices.be 3/5

ST	TATUS: ACCEPTABLE / USAGE DAMAGE									
Во	dywork \& windows									
[x]	REAR DOOR/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE							
[x]	REAR MUDGUARD/LEFT/REAR		SCRATCH WITH PAINT DAMAGE							
[x]	REAR MUDGUARD/LEFT/CENTER		SCRATCH (WITHOUT PAINT DAMAGE) POL.						
[x]	REAR DOOR/LEFT/FRONT		SCRATCH (WITHOUT PAINT DAMAGE) POL.						
[x]	REAR DOOR/RIGHT/CENTER		SCRATCH (WITHOUT PAINT DAMAGE)						
[x]	WINDSCREEN/CENTER/LEFT		CHIPS							
[x]	FRONT MUDGUARD/LEFT/REAR		DENT							
[x]	FRONT/RIGHT		SCRATCH WITH PAINT DAMAGE							
[x]	FRONT BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE							
Inte	erior									
[x]	DOOR IN FL		OTHER DAMAGES							
Ac	cessories and others									
[x]	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH WITH PAINT DAMAGE							
ST	ATUS: NOT ACCEPTA	BLE								
Во	dywork \& windows									
[x]	REAR BUMPER /LEFT/CORNER		SCRATCH WITH PAINT DAMAGE							
		Repair paint - LI	New paint - E	Depr.	Total					
	2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR					
Inte	erior									
[x]	DOOR IN REAR L		HOLE							
	Number Code	Description	Unit price	Depr.	Total					

l	1	2	3	4	5	6	7	8	9	10
	82.20	211.80	0	0	0	0	0	0	0	0
	82.20	105.90	0	0	0	0	0	0	0	0

82.20 EUR

82.20 EUR

VINYL REPAIR



www.vabfleetservices.be Date: 13/10/2017 4/5

INNOVATIVE	TRADITIONAL	GENERAL		
82.20	211.80	0		294.00
HOG: 0	BG: 0		NA Deprec.	188.10
			0.00%	
			TOTAL	188.10



www.vabfleetservices.be Date: 13/10/2017 5/5

[x] = Status Modification

Pictures: No CIRCUMSTA	ANCES			NORMAL CONCL	USION		
Extra Time :	0 min	Waiting t Reason :	ime: 0 min		Towing time: 0 min Reason:		
NOT EXECUTED : Reason :	No				<u> </u>		
Remark:	NAVI OK [x]						
Prices in EUR with	out VAT						
Authorized by customer:				Executed by VAB Fleet S	ervices		
customer :							
Remark authorized cus	tomer :						
Date :	13/10/2017	Hour :	12:58				
Company:							
Executed by VAB Fleet Services							
E-Mail :	@						
Signature authorized by o	customer						
_			- ب				