

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	129453 KM
File nr. :	1446940	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1AMW475 / WV1ZZZ2KZAX156184 /		yr of constructionr :	/
E-File nr. :		First registration :	11/02/2011
VFS-nr. :		Color :	WHITE
Make + Model :	VOLKSWAGEN / CADDY	Fuel type :	DIESEL
Object nr. :	9461	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KUMPEN NV	Co2:	159g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	CADDY 5d 2.0SDi 5v 70PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	69	kW:	51
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	
Rear tyre	195	65	R	15	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR MUDGUARD/LEFT/CENTER		DENT			
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER		DENT			
	Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR DOOR/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR		238.76 EUR		50 %	238.76 EUR
[x]	WINDSCREEN/LEFT		HOLE/CRACK/TORN			
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		0 EUR		50 %	
			Repair paint - LI	New paint - E	Depr.	Total
3	25 LU =120.00 EUR		0 EUR		50 %	120.00 EUR
[x]	FRONT DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR		238.76 EUR		50 %	238.76 EUR
[x]	FRONT THRESHOLD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		+DEUK	
			Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR		232.88 EUR		50 %	232.88 EUR
[x]	FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 3	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	34.41 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	WIND SCREEN	275.40 EUR	50 %	275.40 EUR

1	2	3	4	5	6	7	8	9	10
34.41	110.64	395.40	63.00	110.64	63.00	477.52	232.88	0	0
34.41	110.64	197.70	63.00	110.64	63.00	238.76	116.44	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
381.69	1105.80	0	1487.49
HOG: 0	BG: 3		NA Deprec. 934.59
			0.00%
			TOTAL 934.59

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/10/2017 Hour : 09:02 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	