

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: DIRTY [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 108777 KM |
| File nr. : | 1450106 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1EAK208 / U5YPC815ADL223404 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 03/10/2012 |
| VFS-nr. : | | Color : | GREEN |
| Make + Model : | KIA / SPORTAGE | Fuel type : | DIESEL |
| Object nr. : | 15844 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | COMPUTER TASK GROUP BELGIUM NV | Co2: | 147g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | SPORTAGE 2WD Fusion 115PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | |
| Variant car: | SUV | Engine size: | 1685 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 116 | kW: | 85 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |

General condition:

| | |
|-------------------------------------|---------------------------|
| Original registr. number : OK | Service manual : [x] |
| Cert. of reg. / Part 1: | Cert. of conformity : OK |
| Cert. of reg. copy / Part 2: OK [x] | Insurance certificate : |
| Warning vest : OK [x] | Transport licence : |
| Tax certificate : | Navigation CD/SD/DVD |
| Fuel card : | Car radio : |
| Mobile phone kit : | Extinguisher : OK [x] |
| First aid kit : OK [x] | Warning triangle : OK [x] |
| Jack, wheelspanner : | Oil level : OK [x] |
| | Filled up : 0 |

Wheels and tyres: Summer tires

| |
|---|
| Wheel FL: [x] HANGKOOK Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RL : [x] DUNLOP Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel FR : [x] HANGKOOK Tyre : [x] OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RR : [x] DUNLOP Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RES: [x] Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 235 | 55 | R | 18 | H |
| Rear tyre | 235 | 55 | R | 18 | H |

Remark :

Wheels and tyres:

| |
|---|
| Wheel FL: Tyre : OK / Rim : / Hubcap : |
| Wheel RL : Tyre : OK / Rim : / Hubcap : |
| Wheel FR : Tyre : OK / Rim : / Hubcap : |
| Wheel RR : Tyre : OK / Rim : / Hubcap : |
| Wheel RES: Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

Conclusion

Bodywork \& windows

[x] REAR DOOR/LEFT/FRONT DENT

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

[x] REAR DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/RIGHT/FRONT DENT

[x] FRONT BUMPER/CENTER/RIGHT CHIPS

[x] FRONT BUMPER/RIGHT/SIDE SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

| | Repair paint - LI | New paint - E | Depr. | Total |
|--------------------|-------------------|---------------|-------|------------|
| 7 15 LU =72.00 EUR | 0 EUR | 235.80 EUR | 50 % | 307.80 EUR |

[x] REAR LIGHT/RIGHT HOLE/CRACK/TORN

| | Repair paint - LI | New paint - E | Depr. | Total |
|-------------------|-------------------|---------------|-------|-----------|
| 7 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |

[x] REAR THRESHOLD/LEFT/REAR DENT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|----------------|-------------|------------|-------|------------|
| 3 | I1 i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | | 115.56 EUR |

[x] REAR DOOR/RIGHT/CORNER/BELOW DENT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|----------------|-------------|------------|-------|------------|
| 4 | I1 i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | | 115.56 EUR |

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------------------|---------------|------------|-------|-----------|
| 4 | I1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |

[x] FRONT THRESHOLD/LEFT/REAR DENT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|----------------|-------------|------------|-------|------------|
| 2 | I1 i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | | 115.56 EUR |

| | | | | | | |
|-----|----------------------------|--------------------------|----------------------|-------------------|--------------|--------------|
| [x] | FRONT DOOR/LEFT/REAR | | DENT | KARATERLIJN | | |
| | | Repair paint - LI | New paint - E | Depr. | Total | |
| 6 | 5 LU =24.00 EUR | 318.35 EUR | | 50 % | 342.35 EUR | |
| [x] | FRONT THRESHOLD/RIGHT/REAR | | DENT | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total | |
| 8 | 15 LU =72.00 EUR | 0 EUR | | 50 % | 72.00 EUR | |
| [x] | BONNET/CENTER/RIGHT/FRONT | | DENT | | | |
| | Number | Code | Description | Unit price | Depr. | Total |
| 5 | I 1 | i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |
| | Number | Code | Description | Unit price | Depr. | Total |
| 5 | I 2 | i-vab-uitd-02 | BEAT OUT DENT SUPPL | 19.80 EUR | | 39.60 EUR |

Interior

| | | | | | |
|-----|-------------------|--------------------------|----------------------|--------------|--------------|
| [x] | FLOOR FL | | HOLE | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 40 LU =192.00 EUR | 0 EUR | | 50 % | 192.00 EUR |
| [x] | FLOOR BOOT | | CARVED | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |
| [x] | BOOT LID IN | | CARVED | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |
| [x] | BOOT IN L | | CARVED | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |
| [x] | BOOT IN R | | CARVED | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |

Accessories and others

| | | | | | | |
|-----|-------------------------------|-------------|---------------------------|-------------------|--------------|--------------|
| [x] | OUTSIDE MIRROR RIGHTHAND SIDE | | SCRATCH WITH PAINT DAMAGE | | | |
| | Number | Code | Description | Unit price | Depr. | Total |
| 10 | I 1 | i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | | 115.56 EUR |

[x] SIDE PROTECTION

SCRATCH (WITHOUT PAINT DAMAGE)

| | Repair paint - LI | New paint - E | Depr. | Total |
|-------------------|-------------------|---------------|-------|-----------|
| 9 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |

Others

CLEANLINESS INTERIOR

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-----------------------------|-------------------|-----------|-----------|
| 1 | I 4 | personenwagen-a-vab-rein-02 | CLEANING INTERIOR | 11.47 EUR | 45.88 EUR |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-----------------|------------|-------|------------|
| 1 | 1 | CARPET | 60.00 EUR | 50 % | 60.00 EUR |
| 1 | 1 | UPHOLSTERY DOOR | 90.00 EUR | 50 % | 90.00 EUR |
| 1 | 1 | UPHOLSTERY DOOR | 90.00 EUR | 50 % | 90.00 EUR |
| 1 | 1 | UPHOLSTERY DOOR | 90.00 EUR | 50 % | 90.00 EUR |
| 1 | 1 | UPHOLSTERY DOOR | 90.00 EUR | 50 % | 90.00 EUR |
| 7 | 1 | REAR LIGHT | 90.00 EUR | 50 % | 90.00 EUR |
| 8 | 1 | DOORSTEP | 250.00 EUR | 50 % | 250.00 EUR |
| 9 | 1 | SIDE PROTECTION | 14.40 EUR | 50 % | 14.40 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|--------|--------|--------|--------|-------|--------|
| 753.88 | 115.56 | 115.56 | 178.56 | 102.60 | 342.35 | 421.80 | 322.00 | 38.40 | 115.56 |
| 399.88 | 115.56 | 115.56 | 178.56 | 102.60 | 171.18 | 210.90 | 161.00 | 19.20 | 115.56 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|----------------------|
| 673.72 | 1832.55 | 0 | 2506.27 |
| HOG: 0 | BG: 0 | | NA Deprec. 1590.00 |
| | | | 0.00% |
| | | | TOTAL 1590.00 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 23/10/2017 Hour : 10:33 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |