

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	143351 KM
<b>File nr. :</b>	1450426	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1HGR668 / WF0GXXGBBGEU70421 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	16/07/2014
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	FORD / MONDEO CLIPPER	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	37065	<b>Fuel :</b>	
<b>Classification :</b>	F	<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	SECURITAS NV	<b>Co2:</b>	120g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	0
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	1997
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	136	<b>kW:</b>	100
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :		
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	FIRESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	FIRESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	FIRESTONE	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	FIRESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	V
Rear tyre	215	60	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT
[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR DOOR/RIGHT/CORNER/BELOW	OTHER DAMAGES	SLECHTE HERSTELLING			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
	0	0				
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
	3	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
[x]	FRONT DOOR/RIGHT/FRONT	DENT				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
	4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE				
		<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
	2	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE				
		<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
	2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

### Interior

[x]	BOOT LID IN	CARVED				
		<b>Repair paint - LI</b>	<b>New paint - E</b>		<b>Depr.</b>	<b>Total</b>
	1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

## Accessories and others

[x] OUTSIDE MIRROR LEFTHAND SIDE

BROKEN / CRACKED

	Repair paint - LI	New paint - E	Depr.	Total
5 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	UPHOLSTERY DOOR	90.00 EUR	50 %	90.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	SIDE INDICATOR	20.40 EUR	50 %	20.40 EUR

1	2	3	4	5	6	7	8	9	10
114.00	431.98	58.80	63.00	44.40	0	0	0	0	0
57.00	215.99	58.80	63.00	22.20	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
121.80	590.38	0	<b>712.18</b>
HOG: 0	BG: 0		NA Deprec. 416.99
			0.00%
			<b>TOTAL 416.99</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 23/10/2017 <b>Hour :</b> 09:58 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	