

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	110001 KM
File nr. :	1442997	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DUR370 / YV1MW84F1C2681592 /		yr of constructionr :	2012 / 09
E-File nr. :		First registration :	03/09/2012
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / V50	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ACERTA CONSULT CVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	V50 BRE DRIVe Start/Stop 99g 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 4-6/ Rim : / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR WINDOW STYLE/CENTER/LEFT/UP	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/LEFT/CENTER	DENT	
[x]	ROOF/REAR/LEFT	SCRATCH WITH PAINT DAMAGE	DEELS NIET DOOR LAK
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	DEELS DOOR LAK
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	DENT		+KRASSEN M LAKSCHADE AANV		
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
3	10 LU	=48.00 EUR	308.20 EUR		50 %	356.20 EUR

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	0	356.20	95.00	0	0	0	0	0	0
63.00	0	178.10	95.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
158.00	356.20	0	514.20
HOG: 0	BG: 0		NA Deprec. 336.10
			0.00%
			TOTAL 336.10

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : KLANT HEEFT DE SCHADE VAN LINKER EN RECHTER ACHTERVLEUGEL REEDS AANGEGEVEN. Date : 20/10/2017 Hour : 09:13 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	