

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	103518 KM
File nr. :	1446115	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1RPR138 / ZAR94000007124339 /		yr of constructionr :	/
E-File nr. :		First registration :	11/01/2012
VFS-nr. :		Color :	BLUE D
Make + Model :	ALFA ROMEO / GIULIETTA	Fuel type :	DIESEL
Object nr. :	5921	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	AUBAY SA	Co2:	114g/km
Driver :		Remote controls:	1
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	45	R	17	W
Rear tyre	225	45	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	DEELS TE POLIEREN
[x]	ROOF /FRONT/LEFT/CENTER	DENT	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR DOOR/CENTER/LEFT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	ROOF STYLE/FRONT/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
5	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	BONNET/CENTER/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	FRONT BUMPER/LEFT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
1	20 LU =96.00 EUR	0 EUR	235.80 EUR	50 %	331.80 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
6	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR

Number	Code	Description	Unit price	Depr.	Total
6	1	MIRROR GLASS	18.00 EUR	50 %	18.00 EUR

1	2	3	4	5	6	7	8	9	10
850.56	211.80	626.55	301.68	63.00	42.00	380.00	290.08	0	0
483.06	105.90	313.28	150.84	63.00	21.00	380.00	145.04	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
558.56	2207.11	0	2765.67
HOG: 0	BG: 0		NA Deprec. 1662.12
			0.00%
			TOTAL 1662.12

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 09:39 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	