

www.vabfleetservices.be Date: 23/10/2017 1/5

CUXB8V

[x] = Status Modification

VAT over the margin - car:

Variant car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner:		Mileage :	42622 KM
File nr. :	1444898	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FJP799 / YV1MV8481E2084	850 /	yr of constructionr :	/
E-File nr. :		First registration :	18/07/2013
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / V40	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	BELGACOM INT. CARRIER SERVICES NV	Co2:	88g/km
Driver :		Remote controls:	
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	V40 D2 Base 115PK	Country registration :	BELGIUM

Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:		1	

Metallic paint:

Engine size:

Yes

1560



www.vabfleetservices.be Date: 23/10/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

#### Wheels and tyres: Summer tires

		r1	XX7: J41.	1		IT-2-1-4			Т	D:		T., J.,,	$\overline{}$
Wheel RES:	[x]		Tyre:	O	K	/	Rim:			/ Hubo	ap:		
Wheel RR:	[x]	MICHELIN	Tyre:	O	X [2	x] 2-4/	Rim:			/ Hubo	ap:		
Wheel FR:	[x]	MICHELIN	Tyre:	[x] O	X [2	[ 2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubo	ap:		
Wheel RL:	[x]	MICHELIN	Tyre:	O	X [2	[ 2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubo	ap:		
Wheel FL:	[x]	MICHELIN	Tyre:	O	X [2	[ 2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubo	ap:		

[x]	Width	Height	Туре	Rim	Index
Front tyre	205	55	R	16	WINTER H
Rear tyre	205	55	R	16	WINTER H

**Remark:** REP SET OK

#### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



RIM REAR LEFT

Number Code

i-vab-herstalu-02

### **APPRAISAL**

23/10/2017 Date: www.vabfleetservices.be 3/5

ST	ATUS: ACCEPTABLE / US	SAGE DAMA	GE			
Во	dywork \& windows					
[x]	REAR BUMPER/LEFT/LEFT		SCRATCH WITH PA	AINT DAMAGE		
x]	REAR LIGHT/RIGHT		SCRATCH WITH PA	AINT DAMAGE		
x]	REAR DOOR/RIGHT/FRONT		SCRATCH (WITHO	UT PAINT DAMAGE	E)	
x]	WINDSCREEN/CENTER/LEFT		CHIPS			
x]	FRONT DOOR/RIGHT/REAR		SCRATCH (WITHO	UT PAINT DAMAGE	E)	
x]	BONNET/CENTER/LEFT/FRONT		CHIPS			
x]	FRONT BUMPER/CENTER/LEFT		CHIPS			
ST	ATUS: NOT ACCEPTABL	E				
Во	dywork \& windows					
x]	REAR DOOR/LEFT/FRONT		DENT			
		Repair paint - LI	New paint - E		Depr.	Total
	2 0 LU =0.00 EUR	435.72 EUR			50 %	435.72 EUR
x]	ROOF STYLE/CENTER/RIGHT		DENT			
		Repair paint - LI	New paint - E		Depr.	Total
	3 0 LU =0.00 EUR	220.18 EUR			1	220.18 EUR
Otl	ners					
	CLEANLINESS INTERIOR					
	Number Code	Description		Unit price	Depr.	Total
	1 I 3 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	R	14.58 EUR	,	43.74 EUR
	RIM FRONT LEFT					
	Number Code	Description		Unit price	Depr.	Total
	4 I 1 i-vab-herstalu-02	REPAIR ALLOY WHE	EL	95.00 EUR		95.00 EUR

Unit price

95.00 EUR

Depr.

Total

95.00 EUR

Description

REPAIR ALLOY WHEEL



www.vabfleetservices.be Date: 23/10/2017 4/5

RIM FRONT RIGHT

Number	Code		Description	Description Unit price					Total	
4 I 1	i-vab-herstalu-02 REPAIR ALLOY WHEEL					95.00 E	UR	'	95.00 EUR	
1	2	3	4	5	6	7	8	9	10	
43.74	435.72	220.18	285.00	0	0	0	0	0	0	
43.74	217.86	220.18	285.00	0	0	0	0	0	0	

		GENERAL	TRADITIONAL	INNOVATIVE
984.64		0	655.90	328.74
766.78	NA Deprec.		BG: 0	HOG: 0
	0.00%			
766 78	TOTAL			



www.vabfleetservices.be Date: 23/10/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES		UNDER CONDITION - VEHICLE VERY DIRTY					
Extra Time :	0 min	Waiting time: 0 mi Reason:	n	Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No							
Remark :								
Prices in EUR v	vithout VAT							
Authorized by customer:			Executed by VAB Flee	t Services				
Remark authorized	customer :							
Date :	23/10/2017	<b>Hour:</b> 11:28						
Company :  Executed by VAB F Services	leet							
E-Mail :	@							
Signature authorized	by customer							