

www.vabfleetservices.be Date: 25/10/2017 1/5

D2JV8J

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 134458 KM File nr. : Mileage start / arrival: 0 / 01450847 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1BHT080 / VF1FW1BH545018367 / E-File nr. : First registration: 01/06/2011 VFS-nr.: Color: WHITE Make + Model : Fuel type : RENAULT / KANGOO EXPRESS **DIESEL** Object nr. : Fuel: 47822 **Environment Class:** Classification: EURO 4 Customer company: Co2: DALKIA SA<ID>2229924</ID> 140g/km Driver : Remote controls: TISSUE Covering: Number keys: 2[x]Vehicle kind: TRUCK, LORRY Seats (minivan): 0 Vehicle type: KANGOO EXPR.B/F MAXI Grand Confort Country registration: **BELGIUM** 86PK

VAI over the margin - car.	140	Wietanic paint.	140
Variant car:	BESTELWAGEN	Engine size:	1461
Gear box :	Manueel	Number of places:	2
Number of gears:	5	Number of doors:	5
HP:	86	kW:	63
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
Ceneral condition:		L	

Metallic paint:



www.vabfleetservices.be Date: 25/10/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Front	t tvre		195				65			R		15	T
		[x]	Width			H	eight			Type		Rim	Index
Wheel RES:	[x]	ANDER	E Tyre:		OK	[x]	2-4 /	Rim :				/ Hubcap :	
		ANDED			0.17		2.4.	ъ.					
Wheel RR:	[x]	UNIRO	YAL Tyre:		OK	[x]	0-1.6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FR:	[x]	UNIRO	YAL Tyre:	[x]	OK	[x]	0-1.6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RL:	[x]	UNIRO	YAL Tyre:		OK	[x]	0-1.6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FL:	[x]	UNIRO	YAL Tyre:		OK	[x]	0-1.6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



25/10/2017 Date: www.vabfleetservices.be 3/5

SEAT UPHOLSTERY TISSUE

Во	dywork \& windows				
[x]	WINDSCREEN/CENTER/RIGHT		CHIPS		
nte	erior				
[x]	FLOOR BOOT		SCRATCHED		
κ]	BOOT IN L		SCRATCHED		
[]	BOOT IN R		SCRATCHED		
/co	cessories and others				
x]	VEH COVERED WITH STICKERS		STICKER(S)		
ST	ATUS: NOT ACCEPTAE	BLE			
30	dywork \& windows				
x]	REAR DOOR/CENTER/RIGHT		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
	3 20 LU =96.00 EUR	226.26 EUR		50 %	322.26 EUF
x]	FRONT DOOR/RIGHT/CENTER		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
	4 25 LU =120.00 EUR	238.76 EUR		50 %	358.76 EUF
κ]	BONNET/CENTER/LEFT		DENT	MET LAKSCH.	ADE
		Repair paint - LI	New paint - E	Depr.	Total
	2 0 LU =0.00 EUR	217.56 EUR		50 %	217.56 EUF
x]	FRONT MUDGUARD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
	4 0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUF
nte	erior				
x]	SEAT FL		BURNT		
		Repair paint - LI	New paint - E	Depr.	Total
	1 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUF
Pie	ces				
	Number Code	Description	Unit price	Depr.	Total

90.00 EUR

50 %

90.00 EUR



www.vabfleetservices.be Date: 25/10/2017 4/5

1	2	3	4	5	6	7	8	9	10
210.00	217.56	322.26	523.89	0	0	0	0	0	0
105.00	108.78	161.13	261.94	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
1273.71		0	1273.71	0
636.86	NA Deprec.		BG: 3	HOG: 0
1	0.00%			
636.86	TOTAL			



www.vabfleetservices.be Date: 25/10/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS	FANCES		NORMAL CONCLUSION						
Extra Time :	0 min	Waiting time: 0 min Reason:	1	Towing time : Reason :	0 min				
NOT EXECUTED : Reason :	No								
Remark:									
Prices in EUR w	rithout VAT								
Authorized by customer :			Executed by VAB Fleet S	Services					
Remark authorized o	customer :								
Date : Company :	25/10/2017	Hour: 14:35							
Executed by VAB Fl Services	leet								
E-Mail :	@								
Signature authorized l	by customer								