

D3ADH1

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	51972 KM
File nr. :	1451399	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1JEZ501 / VF12FL10451113122 /		yr of constructionr :	/
E-File nr. :		First registration :	28/11/2014
VFS-nr. :		Color :	WHITE
Make + Model :	RENAULT / TRAFIC	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	155g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	1598
Gear box :	Manueel	Number of places:	6
Number of gears:	6	Number of doors:	5
HP:	120	kW:	88
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK [x]	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK [x]	Warning triangle :	OK	[x]
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	65	R	16	
Rear tyre	205	65	R	16	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	158.85 EUR		50 %	158.85 EUR
[x]	REAR LIGHT/LEFT/CORNER		HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
4	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	REAR BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE		
	Number	Code	Description	Unit price	Depr.
5	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	110.64 EUR
[x]	FRONT BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	158.85 EUR		50 %	158.85 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE		SCRATCH WITH PAINT DAMAGE		
	Number	Code	Description	Unit price	Depr.
3	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	110.64 EUR

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 5	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR		57.35 EUR

Pieces

	Number	Code	Description	Unit price	Depr.	Total
4	1	REAR LIGHT		67.50 EUR	50 %	67.50 EUR

1	2	3	4	5	6	7	8	9	10
57.35	158.85	110.64	250.35	110.64	0	0	0	0	0
57.35	79.42	110.64	125.18	110.64	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
278.63	409.20	0	687.83
HOG: 0	BG: 3		NA Deprec. 483.23
			0.00%
			TOTAL 483.23

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/10/2017 Hour : 12:01 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	