

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	139153 KM
<b>File nr. :</b>	1448587	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1HUP152 / VF77J9HP8EJ786420 /		<b>yr of constructionr :</b>	2014 / 00
<b>E-File nr. :</b>		<b>First registration :</b>	07/10/2014
<b>VFS-nr. :</b>		<b>Color :</b>	SILVER
<b>Make + Model :</b>	CITROEN / BERLINGO	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	11360	<b>Fuel :</b>	
<b>Classification :</b>	DELIVERY VAN A	<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	FENIOM NV	<b>Co2:</b>	115g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1560
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>	92	<b>kW:</b>	68
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :			
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :			
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :			

  

[x]	Width	Height	Type	Rim	Index
Front tyre	205	65	R	15	H
Rear tyre	205	65	R	15	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] ROOF/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] ROOF STYLE/FRONT/LEFT/CENTER DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

		Repair paint - LI	New paint - E	Depr.	Total
[x]	LIGHTS/LEFT/FRONT				
1	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR
[x]	FRONT BUMPER/RIGHT				
2	0 LU =0.00 EUR	158.85 EUR		50 %	158.85 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FOG LAMP	67.50 EUR	50 %	67.50 EUR

1	2	3	4	5	6	7	8	9	10
115.50	158.85	0	0	0	0	0	0	0	0
57.75	79.42	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	274.35	0	274.35
HOG: 0	BG: 3		NA Deprec. 137.18
			0.00%
			TOTAL 137.18

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 20/10/2017 <b>Hour :</b> 13:45 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	