

D5WYK0

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	101927 KM
File nr. :	1453473	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FCJ162 / VF37J9HP0DJ611063 /		yr of constructionr :	/
E-File nr. :		First registration :	23/05/2013
VFS-nr. :		Color :	BROWN
Make + Model :	PEUGEOT / PARTNER	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BRUXELLES ENERGIE SCRL	Co2:	123g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PARTNER TEPEE 2PLC e-HDi Active 92PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	92	kW:	68
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	FRONT DOOR/LEFT/REAR	DENT

Interior

[x]	DOOR IN FL	SCRATCHED
-----	------------	-----------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
-----	------------------------	---------------------------

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR

[x]	FRONT THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	OP SLUITKANT
-----	----------------------------	---------------------------	--------------

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

[x]	FRONT BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
-----	---------------------------	---------------------------

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	158.85 EUR		50 %	158.85 EUR

1	2	3	4	5	6	7	8	9	10
158.85	238.76	115.56	0	0	0	0	0	0	0
79.42	119.38	115.56	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	397.61	0	513.17
HOG: 0	BG: 3		NA Deprec. 314.36
			0.00%
			TOTAL 314.36

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/10/2017 Hour : 15:33 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	