

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	190686 KM
File nr. :	1451626	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1JFH958 / TMBJG7NE5F0127672 /		yr of constructionr :	/
E-File nr. :		First registration :	03/12/2014
VFS-nr. :		Color :	GREY
Make + Model :	SKODA / OCTAVIA COMBI	Fuel type :	DIESEL
Object nr. :	9461	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KUMPEN NV	Co2:	104g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	ANDERE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	ANDERE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	MICHELIN	Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
3	0	LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR MUDGUARD/LEFT/Front		DENT			
	Number	Code	Description	Unit price	Depr.	Total
6	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	ROOF STYLE/CENTER/RIGHT		DENT			HAGEL
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		97.80 EUR
[x]	FRONT DOOR/LEFT/CENTER		DENT			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR
[x]	FRONT THRESHOLD/RIGHT/Front		DENT			
			Repair paint - LI	New paint - E	Depr.	Total
5	0	LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR
[x]	FRONT MUDGUARD/RIGHT/Front		DENT			
			Repair paint - LI	New paint - E	Depr.	Total
8	0	LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR
[x]	FRONT BUMPER/CENTER/RIGHT		DENT			
			Repair paint - LI	New paint - E	Depr.	Total
4	0	LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	ROOF/CENTER/LEFT		DENT			HAGEL
	Number	Code	Description	Unit price	Depr.	Total
1	I 2	i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		195.60 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE		WINDOW DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR	0 EUR		50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
7	1	INDICATOR	15.00 EUR	50 %	15.00 EUR

1	2	3	4	5	6	7	8	9	10
293.40	82.80	211.80	211.80	310.50	63.00	15.00	220.18	0	0
293.40	82.80	105.90	105.90	155.25	63.00	7.50	110.09	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
439.20	969.28	0	1408.48
HOG: 0	BG: 0		NA Deprec. 923.84
			0.00%
			TOTAL 923.84

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 24/10/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	