

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	113425 KM
File nr. :	1450019	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DKJ097 / WVWZZZ6RZCY276510 /		yr of constructionr :	/
E-File nr. :		First registration :	08/06/2012
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / POLO	Fuel type :	DIESEL
Object nr. :	15879	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	GRANT THORNTON BEDRIJFSREVISOREN CVBA	Co2:	96g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	POLO BlueMotion Techn.DPF 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :	OK	Extinguisher :	OK
	PARROT	Warning triangle :	OK
First aid kit :	OK	Oil level :	OK [x]
Jack, wheelspanner :	OK	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	CONTINENTAL	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RL :	DUNLOP	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	CONTINENTAL	Tyre :	[x] OK [x]	4-6/	Rim :	/	Hubcap :	SCRATCHED
Wheel RR :	DUNLOP	Tyre :	OK [x]	4-6/	Rim :	/	Hubcap :	SCRATCHED
Wheel RES:	[x]	Tyre :	OK [x]	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	185	60	R	15	H
Rear tyre	185	60	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK /	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
169.44	72.00	64.32	43.74	0	0	0	0	0	0
84.72	36.00	64.32	43.74	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
108.06	241.44	0	349.50
HOG: 0	BG: 1		NA Deprec. 228.78
			0.00%
			TOTAL 228.78

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : VRTG VUIL		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/10/2017 Hour : 09:44 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	