

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	180683 KM
<b>File nr. :</b>	1446071	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FGD354 / VF1JKFJC649420487 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	20/06/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BEIGE
<b>Make + Model :</b>	RENAULT / GRAND ESPACE	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	44626	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	ALSTOM BELGIUM SA (4700001191)	<b>Co2:</b>	150g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	PARTIAL LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	7 [x]
<b>Vehicle type :</b>	GR.ESPACE Alcantara 149PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	MONOVOLUME	<b>Engine size:</b>	1995
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	7
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	150	<b>kW:</b>	110
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2/	Rim :		/	Hubcap :
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	1.6-2/	Rim :		/ Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	>6/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	V
Rear tyre	225	55	R	17	W

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	MEERDERE
[x]	BONNET/CENTER/RIGHT	CHIPS	
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE	

### Interior

[x]	SEAT FL	OTHER DAMAGES
-----	---------	---------------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
1	15 LU =72.00 EUR	369.84 EUR		50 %	441.84 EUR

1	2	3	4	5	6	7	8	9	10
441.84	0	0	0	0	0	0	0	0	0
220.92	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	441.84	0	<b>441.84</b>
HOG: 0	BG: 2		NA Deprec. 220.92
			0.00%
			<b>TOTAL 220.92</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 24/10/2017 <b>Hour :</b> 15:21 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	