

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

|                                     |                              |                                 |                               |
|-------------------------------------|------------------------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING              | <b>Cleanliness :</b>            | INT: DIRTY [x] EXT: DIRTY [x] |
| <b>Owner :</b>                      |                              | <b>Mileage :</b>                | 159835 KM                     |
| <b>File nr. :</b>                   | 1445799                      | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                              | <b>Mileag ref. service :</b>    | 0                             |
| 1DWL118 / WWZZZ7NZDV010724 /        |                              | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                              | <b>First registration :</b>     | 18/09/2012                    |
| <b>VFS-nr. :</b>                    |                              | <b>Color :</b>                  | BLACK                         |
| <b>Make + Model :</b>               | VOLKSWAGEN / SHARAN          | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 | 55885                        | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             |                              | <b>Environment Class:</b>       | EURO 5                        |
| <b>Customer company :</b>           | Dow Corning Europe sa        | <b>Co2:</b>                     | 143g/km                       |
| <b>Driver :</b>                     |                              | <b>Remote controls:</b>         | 2                             |
| <b>Covering :</b>                   | TISSUE                       | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle kind :</b>               | VEHICLE                      | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               | SHARAN Comfortline BMT 115PK | <b>Country registration :</b>   | BELGIUM                       |

|                                     |         |                            |         |
|-------------------------------------|---------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   | No      | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 |         | <b>Engine size:</b>        | 1968    |
| <b>Gear box :</b>                   | Manueel | <b>Number of places:</b>   | 5       |
| <b>Number of gears:</b>             | 6       | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 116     | <b>kW:</b>                 | 85      |
| <b>Fisc HP</b>                      |         | <b>Imported vehicle:</b>   | No      |
| <b>Animals transported:</b>         | No      | <b>Smoked in vehicle:</b>  | No      |
| <b>Due date vehicle inspection:</b> |         | <b>Extra set of tires:</b> | No      |
|                                     |         | <b>Use:</b>                | Unknown |

**General condition:**

|                              |    |                       |                         |        |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number :   | OK | Service manual :      | OK                      | [x]    |
| Cert. of reg. / Part 1:      |    | Cert. of conformity : | OK                      |        |
| Cert. of reg. copy / Part 2: | OK | [x]                   | Insurance certificate : |        |
| Warning vest :               | OK | [x]                   | Transport licence :     |        |
| Tax certificate :            |    |                       | Navigation CD/SD/DVD    | OK [x] |
| Fuel card :                  |    |                       | Car radio :             | OK [x] |
| Mobile phone kit :           |    |                       | Extinguisher :          | OK [x] |
| First aid kit :              | OK | [x]                   | Warning triangle :      | OK [x] |
| Jack, wheelspanner :         |    |                       | Oil level :             | OK [x] |
|                              |    |                       | Filled up :             | 0      |

## Wheels and tyres: Summer tires

|            |     |             |        |     |     |      |       |       |          |          |
|------------|-----|-------------|--------|-----|-----|------|-------|-------|----------|----------|
| Wheel FL:  | [x] | CONTINENTAL | Tyre : | OK  | [x] | 4-6/ | Rim : | /     | Hubcap : |          |
| Wheel RL : | [x] | CONTINENTAL | Tyre : | OK  | [x] | >6/  | Rim : | /     | Hubcap : |          |
| Wheel FR : | [x] | CONTINENTAL | Tyre : | [x] | OK  | [x]  | 4-6/  | Rim : | /        | Hubcap : |
| Wheel RR : | [x] | CONTINENTAL | Tyre : | OK  | [x] | >6/  | Rim : | /     | Hubcap : |          |
| Wheel RES: | [x] |             | Tyre : | OK  |     | /    | Rim : | /     | Hubcap : |          |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 215   | 60     | R    | 16  | H     |
| Rear tyre  | 215   | 60     | R    | 16  | H     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |   |          |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

|     |                            |                           |
|-----|----------------------------|---------------------------|
| [x] | REAR MUDGUARD/RIGHT/FRONT  | DENT                      |
| [x] | REAR DOOR/LEFT/REAR        | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT MUDGUARD/LEFT/REAR   | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT MUDGUARD/RIGHT/FRONT | SCRATCH WITH PAINT DAMAGE |

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                          |                           |                          |                      |              |
|-----|--------------------------|---------------------------|--------------------------|----------------------|--------------|
| [x] | REAR BUMPER/CENTER/RIGHT | SCRATCH WITH PAINT DAMAGE |                          |                      |              |
|     |                          |                           | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> |
|     |                          |                           |                          |                      | <b>Total</b> |
| 5   | 0 LU =0.00 EUR           |                           | 254.16 EUR               |                      | 50 %         |
|     |                          |                           |                          |                      | 254.16 EUR   |
| [x] | REAR MUDGUARD/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE |                          |                      | +DEUK        |
|     |                          |                           | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> |
|     |                          |                           |                          |                      | <b>Total</b> |
| 4   | 0 LU =0.00 EUR           |                           | 369.84 EUR               |                      | 50 %         |
|     |                          |                           |                          |                      | 369.84 EUR   |
| [x] | BONNET/CENTER/RIGHT      | SCRATCH WITH PAINT DAMAGE |                          |                      |              |
|     |                          |                           | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> |
|     |                          |                           |                          |                      | <b>Total</b> |
| 2   | 0 LU =0.00 EUR           |                           | 348.09 EUR               |                      | 50 %         |
|     |                          |                           |                          |                      | 348.09 EUR   |
| [x] | ROOF/CENTER/LEFT         | SCRATCH WITH PAINT DAMAGE |                          |                      | MEERDERE     |
|     |                          |                           | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> |
|     |                          |                           |                          |                      | <b>Total</b> |
| 3   | 0 LU =0.00 EUR           |                           | 577.80 EUR               |                      | 50 %         |
|     |                          |                           |                          |                      | 577.80 EUR   |

### Others

CLEANLINESS INTERIOR

| Number | Code | Description                          | Unit price        | Depr.     | Total     |
|--------|------|--------------------------------------|-------------------|-----------|-----------|
| 1      | I 4  | specifiek-per-kwartier-a-vab-rein-03 | CLEANING INTERIOR | 14.58 EUR | 58.32 EUR |

| 1     | 2      | 3      | 4      | 5      | 6 | 7 | 8 | 9 | 10 |
|-------|--------|--------|--------|--------|---|---|---|---|----|
| 58.32 | 348.09 | 577.80 | 369.84 | 254.16 | 0 | 0 | 0 | 0 | 0  |
| 58.32 | 174.04 | 288.90 | 184.92 | 127.08 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                     |
|------------|-------------|---------|---------------------|
| 58.32      | 1549.89     | 0       | <b>1608.21</b>      |
| HOG: 0     | BG: 2       |         | NA Deprec. 833.26   |
|            |             |         | 0.00%               |
|            |             |         | <b>TOTAL 833.26</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                           |  |   |
|---------------------------|--|---|
| <b>Extra Time :</b> 0 min | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No  |  |   |
| <b>Reason :</b>           |  |   |
| <b>Remark :</b>           |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 20/10/2017 <b>Hour :</b> 11:23<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br><br>   |                                |