

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	169468 KM
File nr. :	1451211	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DST159 / TMBJJ73T9D9011726 /		yr of constructionr :	/
E-File nr. :		First registration :	14/08/2012
VFS-nr. :		Color :	GREY
Make + Model :	SKODA / SUPERB	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	UNISYS BELGIUM NV	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	SUPERB COMBI GreenLin.Ambition DPF 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED / Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED / Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT		DENT					
				Repair paint - LI	New paint - E		Depr.	Total
3	0 LU =0.00 EUR			211.80 EUR			50 %	211.80 EUR
[x]	REAR WINDOW/LEFT		SCRATCH WITH PAINT DAMAGE					
				Repair paint - LI	New paint - E		Depr.	Total
4	0 LU =0.00 EUR			0 EUR			50 %	
				Repair paint - LI	New paint - E		Depr.	Total
4	25 LU =120.00 EUR			0 EUR			50 %	120.00 EUR
[x]	REAR DOOR/RIGHT/FRONT		DENT					
	Number	Code	Description		Unit price		Depr.	Total
5	I 1	i-vab-uitd-01	BEAT OUT DENT		63.00 EUR			63.00 EUR
[x]	WINDSCREEN/CENTER/RIGHT		WINDOW DAMAGE				HERSTELD	
	Number	Code	Description		Unit price		Depr.	Total
0	0							
[x]	FRONT MUDGUARD/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE				+DEUK	
				Repair paint - LI	New paint - E		Depr.	Total
2	0 LU =0.00 EUR			220.18 EUR			50 %	220.18 EUR
[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE					
				Repair paint - LI	New paint - E		Depr.	Total
1	0 LU =0.00 EUR			211.80 EUR			50 %	211.80 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	220.18	211.80	370.00	63.00	0	0	0	0	0
105.90	110.09	105.90	185.00	63.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	1013.78	0	1076.78
HOG: 0	BG: 0		NA Deprec. 569.89
			0.00%
			TOTAL 569.89

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 23/10/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	