

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	17852 KM
File nr. :	1450042	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1SGP652 / YV1DZARCDH2158976 /		yr of constructionr :	/
E-File nr. :		First registration :	09/05/2017
VFS-nr. :		Color :	BLACK
Make + Model :	VOLVO / XC60	Fuel type :	DIESEL
Object nr. :	706498	Fuel :	
Classification :		Environment Class:	EURO 6
Customer company :	CVBA VERKOOP EN FABRICATIE VAN METAALPRO	Co2:	124g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1969
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x] PIRELLI	Tyre :	OK [x] 4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x] PIRELLI	Tyre :	OK [x] 2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x] PIRELLI	Tyre :	[x] OK [x] 4-6/	Rim :	/	Hubcap :	
Wheel RR :	[x] PIRELLI	Tyre :	OK [x] 4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x] PIRELLI	Tyre :	OK /	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	235	65	R	17	W
Rear tyre	235	65	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK /	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/RIGHT CHIPS
- [x] REAR DOOR/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR DOOR/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-pol-01	POLISH SCRATCH (<15CM)	43.44 EUR		43.44 EUR

- [x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Interior

- [x] DOOR IN REAR RIGHT CARVED

	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	UPHOLSTERY DOOR	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
114.00	115.56	43.44	0	0	0	0	0	0	0
57.00	115.56	43.44	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
159.00	114.00	0	273.00
HOG: 0	BG: 0		NA Deprec. 216.00
			0.00%
			TOTAL 216.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 19/10/2017 Hour : 16:03 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	