

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|---------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 134210 KM |
| File nr. : | 1448597 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1DJN306 / WVWZZZ7NZCV048015 / | | yr of constructionr : | 2012 / 00 |
| E-File nr. : | | First registration : | 04/06/2012 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | VOLKSWAGEN / SHARAN | Fuel type : | DIESEL |
| Object nr. : | 714151 | Fuel : | |
| Classification : | I | Environment Class: | EURO 5 |
| Customer company : | ALMEX INTERPACK NV | Co2: | 143g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 7 [x] |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|------------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | MONOVOLUME | Engine size: | 1968 |
| Gear box : | Manueel | Number of places: | 7 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 136 | kW: | 100 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | |
|------------------------------|--------|-------------------------|----|
| Original registr. number : | OK | Service manual : | OK |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | OK | Insurance certificate : | |
| Warning vest : | OK [x] | Transport licence : | |
| Tax certificate : | | Navigation CD/SD/DVD | |
| Fuel card : | | Car radio : | OK |
| Mobile phone kit : | | Extinguisher : | OK |
| First aid kit : | OK | Warning triangle : | OK |
| Jack, wheelspanner : | | Oil level : | OK |
| | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | |
|------------|-------------|--------|----|-----|-------|---|----------|
| Wheel FL: | CONTINENTAL | Tyre : | OK | >6/ | Rim : | / | Hubcap : |
| Wheel RL : | CONTINENTAL | Tyre : | OK | >6/ | Rim : | / | Hubcap : |
| Wheel FR : | CONTINENTAL | Tyre : | OK | >6/ | Rim : | / | Hubcap : |
| Wheel RR : | CONTINENTAL | Tyre : | OK | >6/ | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 215 | 60 | R | 16 | H |
| Rear tyre | 215 | 60 | R | 16 | H |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE DEURRAND

Interior

- BOOT LID IN SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR DOOR/RIGHT/CENTER DENT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-------------------|---------------|------------|-------|-----------|
| 1 | I 1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |

- [x] FRONT DOOR/RIGHT/REAR DENT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-------------------|---------------|------------|-------|-----------|
| 2 | I 1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |

- [x] FRONT MUDGUARD/RIGHT/FRONT DENT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-------------------|---------------|------------|-------|-----------|
| 3 | I 1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|-------|-------|---|---|---|---|---|---|----|
| 63.00 | 63.00 | 63.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 63.00 | 63.00 | 63.00 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|-------------------|
| 189.00 | 0 | 0 | 189.00 |
| HOG: 0 | BG: 2 | | NA Deprec. 189.00 |
| | | | 0.00% |
| | | | TOTAL 189.00 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------------------------|------------------------------------------------|-----------------------------------------------|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : NAVI OK | | |

Prices in EUR without VAT

| | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 20/10/2017 Hour : 15:12 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |